

COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Stone City Mine	M-1990-143	Clay (general)	Pueblo
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Tyler V. O'Donnell	June 28, 2016	10:00
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
General Shale Brick, Inc.	Jason McGraw	110c - Constructi	on Limited Impact

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	Complete Bond	\$5,000.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	None
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear	Tyler O'permell	August 30, 2016
	all connect	

GENERAL INSPECTION TOPICS

The following list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each

(AR) RECORDS <u>PB</u>	(FN) FINANCIAL WARRANTY <u>N</u>	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING <u>N</u>	(SF) PROCESSING FACILITIES <u>N</u>	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE <u>N</u>	(RV) REVEGETATION <u>N</u>
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN <u>N</u>	(CI) COMPLETE INSP <u>N</u>
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION <u>N</u>	(RS) RECL PLAN/COMP <u>N</u>
(AT) ACID OR TOXIC MATERIALS <u>N</u>		· · · _

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

The following inspection topics were identified as having Problems or Possible Violations. OPERATORS SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF THE PERMIT AND APPLICABLE RULES AND REGULATIONS. If a Possible Violation is indicated, you will be notified under separate cover as to when the Mined Land Reclamation Board will consider possible enforcement action.

INSPECTION TOPIC: Availability Of Records

PROBLEM: Rule 1.13 states, if an Operator temporarily ceases production of the mining operation for one hundred eighty (180) days or more, the Operator must file a Notice of Temporary Cessation in writing to the Office.

CORRECTIVE ACTIONS: The Operator must file a notice of Temporary Cessation, pursuant to Rule 1.13.5.

CORRECTIVE ACTION DUE DATE: 10/31/2016

OBSERVATIONS

This normal routine monitoring inspection was conducted by Tyler O'Donnell of the Division of Reclamation, Mining and Safety (Division). General Shale Brick, Inc. (Operator), was represented by Jason McGraw and Harold Stickler during the inspection.

The Stone City Mine is located in Pueblo County approximately 18 miles Northwest of Pueblo, Colorado. The Stone City Mine is a 9.8-acre 110c Construction Materials Reclamation Permit. The primary commodity that has been mined at the site was clay. The 110c Construction Materials Reclamation Permit was issued in March of 1991. The approved post-mining land use is rangeland.

No problems or possible violations were observed during the inspection. During the inspection, the sky was clear and the ground was dry. Portions of the affected land lay over top of a historic mining related disturbance. The site has remained inactive for what appears to be a long period of time, this will be cited as a problem for failure to comply with Rule 1.13. Rule 1.13 states, if an Operator temporarily ceases production of the mining operation for one hundred eighty (180) days or more, the Operator must file a Notice of Temporary Cessation in writing to the Office. There was no evidence of excessive erosion, the site appears stable. There appeared to be no significant impacts to the prevailing hydrologic balance. Much of the historic disturbance has begun to fill in with volunteer vegetation. The reclamation cost estimate for this site was updated during the file review for this inspection. It was determined that the current required financial warranty amount is adequate.

Inspection Contact Address

Jason McGraw General Shale Brick, Inc. 1845 West Dartmouth Avenue Denver, CO 80110

Enclosure:Temporary Cessation notice formec:Wally Erickson, DRMS
Elliott Russell, DRMS

PERMIT #: M-1990-143 INSPECTOR'S INITIALS: TOD INSPECTION DATE: June 28, 2016

PHOTOGRAPHS









COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY 1313 Sherman Street, Room 215, Denver, Colorado 80203 Phone (303) 866-3567

TEMPORARY CESSATION NOTICE

(mining activities temporarily cease for more than a one-year period)

Today's date:			
Permit number: M	Site name:		
County:		TC number:	(DRMS use only)
Permittee making request:			
Operator (if other than permittee):			
Date the initial five-year period of	Temporary Cessation begins		
Reason mining activities (material	ls extraction, processing, hau	ling) have ceased:	
Description of plan to resume oper	rations:		
Description of plan to meet perfor monitoring, signs, markers, etc.):			·
Number of affected acres:			
Amount of financial warranty (bo	nd) on deposit with the state:	\$	
Required fees for Temporary Cess for Temporary Cessation):	sation by permit type (please	mark the correct fee and su	bmit it with this request
Permit type Construction Materials	<u>Required 7</u> \$144	<u>"R fee Submit</u>	<u>ted</u> (mark only one)
Hard Rock/ Metal Mining	\$115		
The above-referenced permit ha	s entered Temporary Cessa	ation. This site has reserv	es remaining to be mined.
Operator's signature:			

Please note:

1. While in Temporary Cessation, the operator must continue to comply with the Rules and Act, including maintaining the site, and must continue to file an annual report and annual fee.