



**COLORADO**

**Division of Reclamation,  
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

October 3, 2016

Nick Michael  
Union Milling Company  
P.O. Box 620490  
Littleton, CO 80162

RE: Leadville Mill; DRMS File No. M-1990-057; Receipt of Corrective Action  
Documentation

Dear Mr. Michael,

The Division of Reclamation, Mining and Safety (Division) received your above referenced response in regard to Compliance Problem 1 identified in the report of the inspection that was conducted on August 3, 2016. The status of the corrective action reported by Union Milling Company in regard to this problem is as follows:

**Compliance Problem 1: The stockpile located on the north side of the tailings storage facility, which contains acid generating materials, is coming into contact with stormwater.**

This problem is considered abated as a result of the Operator's submittal of report showing the clean out of the drain pipe below the stockpile and the installation of silt fencing around the drain pipe inlet.

If you have any questions, please contact me at (303) 866-3567 x8116.

Sincerely,

Michael A. Cunningham

CC: Dustin Czapla, DRMS

