



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

October 17, 2016

Suzanne Theisen
Theisen Mineral
1251 Bailey Dr.
Brighton, CO 80603

RE: Suzanne Marie; DRMS File No. M-2009-093; Corrective Action Resolution Notice

Dear Ms. Theisen,

The Division received your above referenced response to the Compliance Problems listed in the Division's report of the inspection that was conducted on August 19, 2016. The status of the corrective actions reported by Theisen Mineral in regard to these problems are as follows:

Compliance Problem 1: The point of contact for the Suzanne Marie site is no longer valid and the Permittee's registration with the Colorado Secretary of State is no longer valid.

This problem is considered abated as a result of the submittal of documentation which demonstrates Theisen Mineral's registration with the Colorado Secretary of State is valid.

Compliance Problem 2: The mine identification sign and affected area boundary markers were not observed per the requirements of Rule 3.1.12.

The Operator submitted photographs of the permit sign and requested an extension of the corrective action date (June 15, 2017) to post the missing boundary markers. This problem will be abated when the Division's receives photographic documentation that the boundary markers have been posted.

Compliance Problem 3: Trash and refuse was noticed on the site.

This problem is considered abated as a result of the submittal of photographs which show the refuse has been removed from the site.

If you have any questions, please contact me at (303) 866-3567 x8116

Sincerely,

Michael A. Cunningham
Environmental Protection Specialist

