

COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

1313 Sherman Street, Room 215 Denver, CO 80203

December 16, 2016

David King Kirkland Construction P.O. Box 580 Rye, CO 81069

RE: Flying Horse Pit; DRMS File No. M-2013-012; Receipt of Corrective Action Documentation

Dear Mr. King,

The Division received your above referenced response in regard to Compliance Problem 1 identified in the Division's report of the inspection that was conducted on October 13, 2016. The status of the corrective action reported by Kirkland Construction in regard to this problem is as follows:

Compliance Problem 1: The mine identification sign was not posted at the site entrance. This problem is considered to be resolved as a result of the submittal of a photograph showing the mine identification sign at the site entrance.

If you have any questions, please contact me at (303) 866-3567 x8116

Sincerely,

Michael A. Cunningham Environmental Protection Specialist

