

COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

1313 Sherman Street, Room 215 Denver, CO 80203

December 27, 2016

Jo Ann Vota 315 N. Sunburst Ln. Durango, CO 81301

RE: Hillyer Pit, Permit No. M-1982-011, Inspection Problem Abated

Dear Mrs. Vota:

On October 4, 2016 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. The lack of the proper Mine Identification Sign and Permit Boundary Markers was cited as a problem with corrective actions required.

On December 23, 2016 the Division received the above mentioned documentation. In addition to the corrective action documentation, The Division was contacted by you consultant and discussed a plan for final resolution of the problem when the snow melts this spring. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203, by phone at 970-243-6368 or by email at lucas.west@state.co.us.

Sincerely,

Lucas West Environmental Protection Specialist Department of Natural Resources Division of Reclamation, Mining and Safety Phone: (970) 243-6368

Cc:

Russ Means, Senior Environmental Protection Specialist

