



**COLORADO**

**Division of Reclamation,  
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

March 31, 2017

Mr. Michael D Krauth  
KrauthCo Inc  
1068 Red Canyon Road  
Cañon City, CO 81212

**Re: J&J Stone Pit #1, Permit No. M-2011-004,  
Documentation of Corrective Action(s) Received**

Dear Mr. Krauth:

On March 27, 2017 the Division of Reclamation, Mining and Safety received your response via email, regarding the Problem identified during the February 16, 2017 inspection conducted at the J&J Stone Pit #1 and cited in the inspection report dated March 2, 2017. The Division has changed the status of the Corrective Action associated with the following cited Problem to be resolved:

*Problem/Possible Violation: The affected area boundary markers are incorrectly placed. This is a problem for failure to maintain boundary markers around the affected area as required by Section 3.1.12(2) of the rule.*

The Operator's representative submitted revised maps for Exhibits C and F as part of the AM-01 review process stating research determined the "GPS data and physical feature locations do not support the Section 3/2 line as represented on the USGS 1954 quadrangle map". Therefore, this Problem is considered resolved.

If you have any questions or need further information, please contact me at (303)866-3567 x8169.

Sincerely,

Timothy A. Cazier, P.E.  
Environmental Protection Specialist

ec: DRMS file  
Angela Bellantoni, Ph.D., EAI

