




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

| | | | |
|---|--|---|------------------------------|
| MINE NAME: Lost Cause Pond | MINE/PROSPECTING ID#: M-2010-084 | MINERAL: Borrow material for | COUNTY: Rio Blanco |
| INSPECTION TYPE: Monitoring | INSPECTOR(S): Travis H. Marshall | INSP. DATE: March 28, 2017 | INSP. TIME: 13:00 |
| OPERATOR: Lost Cause, LLC | OPERATOR REPRESENTATIVE: Dean Mantle | TYPE OF OPERATION: 110c - Construction Limited Impact | |
| REASON FOR INSPECTION: Normal I&E Program | BOND CALCULATION TYPE: Complete Bond | BOND AMOUNT: \$7,000.00 | |
| DATE OF COMPLAINT: NA | POST INSP. CONTACTS: None | JOINT INSP. AGENCY: None | |
| WEATHER: Raining | INSPECTOR'S SIGNATURE:  | SIGNATURE DATE: April 4, 2017 | |

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

| | | |
|---|---|----------------------------------|
| (AR) RECORDS----- <u>Y</u> | (FN) FINANCIAL WARRANTY----- <u>Y</u> | (RD) ROADS----- <u>Y</u> |
| (HB) HYDROLOGIC BALANCE----- <u>Y</u> | (BG) BACKFILL & GRADING----- <u>Y</u> | (EX) EXPLOSIVES----- <u>NA</u> |
| (PW) PROCESSING WASTE/TAILING---- <u>NA</u> | (SF) PROCESSING FACILITIES----- <u>NA</u> | (TS) TOPSOIL----- <u>Y</u> |
| (MP) GENL MINE PLAN COMPLIANCE- <u>Y</u> | (FW) FISH & WILDLIFE----- <u>Y</u> | (RV) REVEGETATION---- <u>Y</u> |
| (SM) SIGNS AND MARKERS----- <u>Y</u> | (SP) STORM WATER MGT PLAN---- <u>NA</u> | (CI) COMPLETE INSP---- <u>Y</u> |
| (ES) OVERBURDEN/DEV. WASTE----- <u>NA</u> | (SC) EROSION/SEDIMENTATION--- <u>Y</u> | (RS) RECL PLAN/COMP-- <u>Y</u> |
| (AT) ACID OR TOXIC MATERIALS----- <u>NA</u> | (OD) OFF-SITE DAMAGE----- <u>Y</u> | (ST) STIPULATIONS----- <u>NA</u> |

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted as part of the normal monitoring program established by the Colorado Division of Reclamation, Mining and Safety (Division). The Lost Cause Pond is located approximately 2 miles south of Rio Blanco County Road 26. The site is a 110c operation with 9.9 permitted acres, only 4.5 acres appeared to be affected during the inspection. Dean Mantle was the permit representative present during the inspection.

A sign located at the main entrance and permit area boundaries were observed and in compliance with Rule 3.1.12.

The site was inactive during the inspection. Various stockpiles of construction material were observed adjacent to the pond that was located in the middle of the area of disturbance.

It appeared that the operation was in compliance with the approved mine plan. No problems or possible violations were observed during the inspection.

In an effort to ensure that the financial warranty remains adequate to reclaim the site per the requirements of the approved reclamation plan, DRMS conducts routine reclamation cost estimates. DRMS staff has determined that the currently held reclamation bond in the amount of \$7,000.00 is adequate to reclaim the site.

Photos that show the conditions observed during the March 28, 2017 inspection are included at the end of this report.

Responses to this inspection report should be directed to Travis Marshall at the Division of Reclamation, Mining and Safety, Grand Junction Field Office, 101 South 3rd Street, Room 301, Grand Junction, Colorado 81501, phone no. 970-241-2042.

PHOTOGRAPHS



Inspection Contact Address

Mike Frick
Lost Cause, LLC
P.O. Box 266
Loma, CO 81524