

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:		MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Henderson Mine		M-1977-342	Molybdenum	Clear Creek, Grand
INSPECTION TYPE:		INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring		Peter S. Hays	April 27, 2017	09:00
OPERATOR:		OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Climax Molybdenum Company		Tim Haynes	112d-3 - Designated Mining Operation	
			1	
REASON FOR INSPECTION:		BOND CALCULATION TYPE:	BOND AMOUNT:	
Normal I&E Program		Partial Bond	\$37,993,785.00	
DATE OF COMPLAINT:		POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA		None	None	
WEATHER:	INSPECTOR'S SIGNATURE:		SIGNATURE DATE:	
Inclement/prevented Inspection	Style		May 3, 2017	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>N</u>	(FN) FINANCIAL WARRANTY N	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES \underline{N}	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- N	(FW) FISH & WILDLIFE \underline{N}	(RV) REVEGETATION N
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN N	(CI) COMPLETE INSP N
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION \underline{N}	(RS) RECL PLAN/COMP N
(AT) ACID OR TOXIC MATERIALS N	(OD) OFF-SITE DAMAGE <u>N</u>	(ST) STIPULATIONS <u>N</u>

 $Y = Inspected \ and \ found \ in \ compliance \ / \ N = Not \ inspected \ / \ NA = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ cited \ A = Not \ applicable \ to \ this \ operation \ / \ PB = Problem \ cited \ / \ PV = Possible \ violation \ violation \ violation \ v$

PERMIT #: M-1977-342 INSPECTOR'S INITIALS: PSH INSPECTION DATE: April 27, 2017

OBSERVATIONS

The scheduled monitoring inspection of the Henderson Mine and Mill by Peter Hays and Stephanie Mitchell with the Division of Reclamation, Mining and Safety (Division/DRMS) was cancelled due to snow and poor visibility and road conditions. Mr. Tim Haynes with Climax Molybdenum - Henderson Operations was notified of the cancelled inspection.

Inspection Contact Address

Mr. Tim Haynes Climax Molybdenum Company 19302 County Rd. #3 Parshall, CO 80468

Ec: Wally Erickson, DRMS