

MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Sweeney Pit No 30	M-1980-239	Sand and gravel	Moffat
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Monitoring	Amy C. Yeldell	April 26, 2017	12:35
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Moffat County	Dan Miller	112c - Construction Regular Operation	
DE LOON FOR INGREGATION	DONE GALOW A FROM FINE	DOME AMOUNT	
REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:	
Normal I&E Program	None	\$0.00	
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA	None	None	
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DAT	E:
Raining	Amy Geldell	May 9, 2017	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY NA	(RD) ROADS <u>Y</u>
(HB) HYDROLOGIC BALANCE <u>Y</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>NA</u>
(PW) PROCESSING WASTE/TAILING N	(SF) PROCESSING FACILITIES NA	(TS) TOPSOIL \underline{Y}
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE \underline{Y}	(RV) REVEGETATION <u>Y</u>
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN N	(CI) COMPLETE INSP <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION <u>Y</u>	(RS) RECL PLAN/COMP <u>Y</u>
(AT) ACID OR TOXIC MATERIALS NA	(OD) OFF-SITE DAMAGE <u>N</u>	(ST) STIPULATIONS \underline{Y}

Y = Inspected and found in compliance / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

PERMIT #: M-1980-239 INSPECTOR'S INITIALS: ACY INSPECTION DATE: April 26, 2017

OBSERVATIONS

This inspection was conducted as part of the Colorado Division of Reclamation, Mining and Safety normal monitoring program. The Sweeney Pit No. 30 is a 112c permitted site that includes a total of 50 permitted acres. The site is located on Bureau of Land Management land. It is located approximately 11 miles southeast of Maybell, Colorado and is accessed from Moffat County Road 17. Dan Miller represented Moffat County and accompanied Amy Yeldell of the Division on the inspection.

The mine identification sign and affected area boundary markers are in place and in compliance with Rule 3.1.12. The sign is located at the entrance of the permit boundary next to the gate. T-posts have been placed to clearly delineate permit boundaries. The key corners are marked with posts that state "permit boundary" as well.

The site is currently not active. No equipment or fuel is stored on site. Stockpiles are present and stable with some minor erosion. Intermittently stockpiled material is trucked off on an as needed basis. All slopes are no steeper than a 3:1.

The topsoil and overburden piles are stored on the north side. The piles were seeded and have abundant vegetative cover. They are stabilized with the approved seed mix as well as other volunteer species. No weeds were observed.


Due to the inclement weather and recent snow melt significant water retention was observed. This pit is not designed to be a pond or hold water long term.

The contact information for this site is outdated. At your earliest convince please send the Division a letter with new information. Note that you can designate different individuals for the permittee/operator, Permitting and inspection contact.

No bond is required for this site as it is permitted to a government agency. No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to: Amy Yeldell at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@state.co.us

PHOTOGRAPHS



















Inspection Contact Address

Dan Miller Moffat County P.O. Box 667 Craig, CO 81626

Enclosure

EC:

Russ Means, Senior EPS, Grand Junction DRMS Jennifer Maiolo, Little Snake River Field Office, BLM