



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

June 27, 2017

Mike Refer  
Aggregate Industries  
1687 Cole Blvd., Suite 300  
Golden, CO 80401

RE: Morrison Quarry; DRMS File No. M-1973-021; Corrective Action Documentation

Dear Mr. Refer,

The Division received your above referenced response to the Compliance Problems in the Division's report of the inspection that was conducted on February 28, 2017. The status of the corrective actions reported by Aggregate Industries in regards to the problems are as follows:

**Compliance Problem 1: Erosion gullies and ruts were observed below Outfall No. 1.**

This problem is considered abated as a result of the submittal of photographic documentation showing the repair of the erosion gullies and ruts.

**Compliance Problem 2: The 2016 Annual Report did not contain all of the information specified on the Annual Report Form as required by Rule 1.15(1).**

This problem is considered abated as a result of the submittal of a Revised Geotechnical Addendum to the Morrison Quarry Annual Report.

If you have any questions, please contact me at (303)866-3567 x8116.

Sincerely,

Michael A. Cunningham  
Environmental Protection Specialist

CC: Connie Davis, Aggregate Industries

