



STATE OF
COLORADO

Musick - DNR, Jason <jason.musick@state.co.us>

Yoast Mine, C-1994-082, 1st Quarter 2017 Pond Inspection Report Review Letter

1 message

Musick - DNR, Jason <jason.musick@state.co.us>
To: "Blomquist, Miranda" <MBlomquist@peabodyenergy.com>

Wed, Aug 30, 2017 at 2:16 PM

Good afternoon Miranda,

Attached is the Division's review of the 1st quarter pond inspection report associated with the Yoast Mine.

Please let me know if you have any questions or comments.

Thanks,
Jason

--

Jason Musick
Environmental Protection Specialist III
Coal Regulatory Program



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567 x 8134 | F 303.832.8106
1313 Sherman Street, Room 215, Denver, CO 80203
jason.musick@state.co.us | <http://mining.state.co.us>



2Q17_Pond.pdf
125K



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

August 30, 2017

Miranda Kawcak
Peabody Energy, LLC
29515 Routt County Road #27
Oak Creek, CO 84607

RE: Seneca Property, LLC, Seneca Yoast Mine, Permit C-1994-082
Second Quarter 2017 Pond Inspection Report Review

Dear Ms. Kawcak:

Second Quarter 2017 Pond Inspection Report Review

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in compliance with the following CDRMS regulation(s):

4.05.9(17) - Examined at least quarterly by a qualified person designated by the operator, for appearance of structural weakness and other hazardous conditions.

4.05.9(17) - A copy of the report shall be submitted to the Division on a quarterly basis.

The second quarter pond inspection report was received by the Division on 14 August 2017 via email. Pond inspections were conducted by WWC Engineering on 01 May 2017.

It is noted that ponds 010, 011, 011A, 012, 013 and 014 were discharging at the time of the inspections. Maintenance items included the potential damage due to rust at the intake of pond 010 and erosion behind and under the flume of Pond 012. The Division has no adequacy comments concerning this report.

If you have any questions feel free to contact me. (303) 866-3567 ext 8134

Sincerely,

Jason Musick
Environmental Protection Specialist

