

1313 Sherman Street, Room 215 Denver, CO 80203

September 12, 2017

Mr. Larry Chartier 21305 Road 28.5 Brush, CO 80723

## RE: Chartier Pit, M-1984-040, Corrective Action Abated

Dear Mr. Chartier:

The Colorado Division of Reclamation, Mining, and Safety (Division) conducted an inspection of the above referenced site on August 10, 2017. During that inspection the Division cited one problem regarding two missing affected area boundary markers. The Division required you to replace the boundary markers in the correct locations and provide the Division proof of such action.

On September 11, 2017 the Division received an e-mail with photographs of the replaced boundary markers. Given this, the corrective action required from the inspection is considered abated at this time. Thank you for timely addressing this issue.

If you have any questions feel free to contact me at (303) 866-3567, extension 8120.

Sincerely,

Jand Ebert

Jared Ebert Environmental Protection Specialist III

