

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

PERMIT INFORMATION

Permit Number: C-1996-084 Mine Name: Lorencito Canyon Mine Operator: New Elk Coal Company, LLC Operator Address: Mr. Louis Head 12250 Highway 12 Weston, CO 81091

County: Las Animas **Operation Type:** Surface **Permit Status:** Permanent Cessation **Ownership:** Private

Operator Representative Present:

Vince Massarotti, Bill Massarotti, Nick Mason

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

Inspection Start Date: Septembe Inspection Start Time: 13:30 Inspection End Date: Inspection End Time:	r 21, 2017		Inspection Type: Coal Co Inspection Reason: Norm Weather: Clear	A A
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto	r's Sig	nature:	Signature Date:
Robert D. Zuber, P.E.	Phot	D.	21-	
				9/26/2017

Inspection Topic Summary

NA - Air Resource Protection	R - Roads
N - Availability of Records	R - Reclamation Success
NA - Backfill & Grading	N - Revegetation
R - Excess Spoil and Dev. Waste	NA - Subsidence
NA - Explosives	N - Slides and Other Damage
N - Fish & Wildlife	NA - Support Facilities On-site
R - Hydrologic Balance	N - Signs and Markers
Y - Gen. Compliance With Mine Plan	N - Support Facilities Not On-site
N - Other	N - Special Categories Of Mining
NA - Processing Waste	N - Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on September 21, 2017. The weather was clear, and the ground was mostly dry. Vince Massarotti, Bill Massarotti, and Nick Mason of NECC were present for the inspection. The field portion of the inspection was very short due to the landowner's requirements related to hunting season (need to leave the site by 3 PM) and NECC staff schedules (Friday the 22nd was an off day).

EXCESS SPOIL and DEVELOPMENT WASTE - Rule 4.09

Placement; Drainage Control; Surface Stabilization:

Fills 7, 8, and 9 were inspected (Fill 8 from below on the highway and the others from the tops of the fills). All were generally in good condition with good vegetation cover.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Two ponds were inspected: 6 and 9A. Pond 6 was holding water but not discharging. No problems were seen at Pond 6. Pond 9A was only viewed from the fill above. It was holding water, but it could not be seen if it was discharging. The repair on the Pond 9A dam was stable.

During the inspection, NECC staff was cleaning sediment from check dams (which act as sumps) above Pond 6.

ROADS – Rule 4.03 Construction 4.03.1(3)/4.03.2(3) Drainage 4.03.1(4)/4.03.2(4) Surfacing and Maintenance4.03.1(5) and (6)/4.03.2(5) and (6) Reclamation 4.03.1(7)/4.03.2(7):

The ditch beside the road to Pond 6 has been cleared of sediment.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

On the hill above Pond 6, rills are still in need of repair.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Roadside ditch on way to Pond 6



Hillside above Pond 6

Number of <u>Partial</u> Inspection this Fiscal Year: 2 Number of <u>Complete</u> Inspections this Fiscal Year: 1



Fill 7



Fill 9 (repair within circle)

AVAILABILITY OF RECORDS

PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	Expires 11/7/2017	NPDES Permit	CO0048988 (unsigned)
Permit Application w/Revisions	yes	NPDES Records	Q3 2015 (terminated monitoring)
Findings Document	MT4 (Jan. 2016)	Stormwater Management Plan	2007
Insurance Certificate	Exp. April 2018	SPCC Plan	n/a
Bond Document	\$927,121.00	MSHA Pond Inspections	n/a
Phased Bond Release	SL2,		
Documents/Findings	Findings 4/29/08	State Engineer's Pond Inspection	n/a
Air Emission Permits	Terminated	Quarterly Pond Inspections	Q3 2016
County Special Use Permits	SUP-01-020	Annual Hydrology Reports	Terminated
UG Mining Landowner Notification	n/a	 Ground Water Monitoring 	
Subsidence Monitoring Reports	n/a	• Surface Water Monitoring	
Subsidence Monitoring Data	n/a	 Spring & Seep Monitoring 	
Rill & Gully Survey	n/a	 Mine Water Discharge Monitoring 	
Vegetation Monitoring Data		Mine Inflow Study	
Specific Variance Approvals	n/a	Water Consumption Records	
Annual Reclamation Reports	2016	1	201451, 201453-
*		Well Permits	201476
Midterm Review Documents	MT4 (findings Jan. 2016)		
DRMS/OSM Inspection	Through		
Reports/Enforcement Actions	July 2017	BLASTING RECORDS	
Transfers/Succession of Operator	Executed 2008	Blasting Publication	n/a
Temporary Cessation Notification	n/a	Blasting Records (3 years)	n/a
Reclamation Cost Estimate	RN3, \$916,169	ATFE Explosives Permit	n/a
CERTIFICATIONS		Blasting Variances	n/a
Pond Certifications	Yes, Exhibit 15	Pre-Blast Surveys	n/a
Annual Certifications for Impoundments	n/a		
Fill Certifications for Excess Spoil or Underground Development Waste	yes	ADDITIONAL RECORDS (specify)	
Quarterly Inspections	Q2 2017	None at this time	
Compaction Testing			
• Final Certification			
Coal Processing Waste Banks	n/a		
Haul Road Certifications	yes		
Access Road Certifications	yes		

Number of <u>Partial</u> Inspection this Fiscal Year: 2 Number of <u>Complete</u> Inspections this Fiscal Year: 1