

October 18, 2017

Colorado Division of Reclamation, Mining, and Safety Attention: Minerals Program 1313 Sherman St., Room 21 Denver, CO 80203-2273

RE: 2017 Annual Report for Bulldog Mine Operation, Permit No. M-1977-215

Dear Minerals Program,

The Bulldog Mine Operation remains in Temporary Cessation in 2017 and there were no changes or activity from October 31, 2016 to October 30, 2017.

RGS continues to keep all permitting current and the assessment of the economics of the Bulldog Project is ongoing. Until the project is determined to be economically viable, construction and operation of future components like water treatment, additional waste rock storage, mining and milling operations and tailings disposal are not currently envisioned. The EPP will be amended to include these future components once the decision is made to construct such facilities.

Disturbance

There was no new disturbance from October 31, 2016 through October 30, 2017.

Reclamation

Monitoring of re-seeding areas throughout the Bulldog Project was ongoing and no re-seeding was conducted from October 31, 2016 through October 30, 2017. RGS will continue to monitor these areas.

Weed spraying was conducted from September 1 through September 8, 2017 on the following areas showing signs of noxious weeds; 9400 Portal Area, see Figure 1. The W and NW corner of TP-2 area, see Figure 2. A four gallon back pack weed sprayer was used to apply Milestone weed spray in order to control Canada thistle growth.

Other Items

The site remains in Temporary Cessation and the security of site facilities is monitored on a regular basis and gates to site entrances are kept locked.

Monitoring well water levels in BD-MW, HW-3 were recorded on October 13, 2017. Water level in HW-4 was not recorded. See Figure 7.

Annual water quality results for Windy Gulch surface and groundwater samplings have been submitted to DRMS. Surface water analytical results were submitted in June and groundwater analytical results were submitted in October. See Figure 3 for Surface water results and Figure 4 for groundwater results.

The Bulldog Mine Operation permit boundary map is included. See Figure 9.

Please call or email if you have any questions or need additional information.

Randy McClure Consultant PO Box 610 625 USFS Road 504.1A Creede, CO 81130 ph: 719.658.1080 ext 2701 cell: 970.317.5355

rmcclure@hecla-mining.com

fax: 719.658.1082