



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, Colorado 80203

October 31, 2017

Mike Bynum
Colorado Milling Company, LLC
50 West 100 South Street
Moab, UT 80342

**Re: Gold Hill Mill, Permit No. M-1994-117, Receipt of Corrective Action Documentation,
Compliance with Mine Plan**

Mr. Bynum:

On October 27, 2017, the Division of Reclamation, Mining, and Safety (Division) received your Corrective Action documentation regarding the problem identified during the inspection conducted at the Gold Hill Mill site on August 1, 2017. The status of the Corrective Action associated with this problem is as follows:

Corrective Action Documentation: The operator submitted photographic documentation showing the tailings have been relocated inside the tailings impoundment to allow for a minimum two feet freeboard around the perimeter of the impoundment in accordance with the approved mining plan.

Corrective Action Status: The Division considers the problem to be abated.

If you have any questions, please contact me by telephone at 303-866-3567, ext. 8129, or by email at amy.eschberger@state.co.us.

Sincerely,

Amy Eschberger
Environmental Protection Specialist

EC: Mark Steen at: goldtontine@gmail.com
Wally Erickson, DRMS at: (wally.erickson@state.co.us)

