

Cazier - DNR, Tim <tim.cazier@state.co.us>

RE: [EXTERNAL] M-1987-171 Fountain Colony Pit Inspection Follow-up

1 message

Nicole.Hapl <Nicole.Hapl@kiewit.com> To: "Cazier - DNR, Tim" <tim.cazier@state.co.us> Wed, Nov 29, 2017 at 3:50 PM

Hi Tim,

- 1.) I have attached an invoice for thistle control and a letter from T-P about the Saltceder tree.
- 2.) I'm looking for the removal in 2003.
- 3.) Topsoil no more has been stockpiled and it has not been spread on pit floor.
- 4.) Will send in the morning



Nicole Hapl-Martinez Plant Engineer 719/393/0026 office 719/393/7418 fax Kiewit Infrastructure 3651 Wabash Street Colorado Springs, CO 80906

From: Cazier - DNR, Tim [mailto:tim.cazier@state.co.us] Sent: Monday, November 27, 2017 10:16 AM To: Nicole.Hapl <Nicole.Hapl@kiewit.com> Subject: [EXTERNAL] M-1987-171 Fountain Colony Pit Inspection Follow-up

Hi Nicole,

I'm trying to finalize the inspection report for my inspection. There are a few items I need to follow up with you:

1) Tamerisk Control. On July 25th we had some back and forth emails addressing control of the Salt Cedar (tamarisk) at the Fountain Colony Pit. Your final email requested what documentation the Division would accept for demonstrating you

State.co.us Executive Branch Mail - RE: [EXTERNAL] M-1987-171 Fountain Colony Pit Inspection Follow-up

had started the required control program. I replied by stating "sending us a copy of their [*TP Enterprises Inc.?*] itemized bill will suffice for our records. We'll also need the bill for cutting 2 years down the road." to date, I have not seen any documentation demonstrating you sprayed the tamarisk/salt cedar. If you can send me that documentation, I can close out the initial treatment portion of the corrective action.

2) Concrete pads: During the inspection, we discussed the concrete pads for the batch plant that was approved in technical revision #2 (TR-02). You thought at the time, the concrete pads were still there but had been covered up with pit run material. You said you would double check. Have you had a chance to double check on that? If they have been removed, can you provide the Division wit a receipt if performed by a contractor, or a work order (or something similar) if done by Kiewit?

3) Topsoil: During the inspection we had some discussion as to whether any more topsoil was stockpiled and if it had beeen spread on the pit floor. I meant to follow-up earlier. Have you received any clarification on topsoil stackpiles and placement?

4) Annual Report: The Division is moving the responsibility for following up on annual report discrepancies to the specialists (like me). Our records indicate no map was sent with the 2017 annual report. This is required by statute (C.R.S. 34-32.5-116(3)(a)). I will try to contact Daniel Leone this week to discuss with him, but it will be listed in the inspection report if I don't recieve the required map.

Please let me know if you have any questions.

Tim Cazier, P.E.

Environmental Protection Specialist

P 303.866.3567 x8169 | F 303.832.8106 | C 303.328.5229

1313 Sherman St., Room 215, Denver, CO 80203

tim.cazier@state.co.us | http://secure-web.cisco.com/1FnIXDywjGt4zmCqZDpnIltiOFvzV6 S7918OCWAiSPF0wQMj9rIVCHp3m0YABcjwpj4v9MS3WgAY1-FhIwY-07PFGcIZhXnJPFpbh1EIW9QjUBOwFw yYQ1j6eouLgR0CIFu-ADiW5XfMJq2g0RyxEYRGDItqN3aKcVemkIJ8yOWU-I97ypX17Ji8mHScBPAIQa9IsjsbtEP gKfg9RW2c22PbWLBUKRuaq8pWsd5A4897OMkrPPahTRvgDoK5v7FTe/http%3A%2F%2Fwww.mining.state.co.us





November 29, 2017

Subject: Kiewit Pit Saltcedar Control

T-P Enterprises, Inc. was unable to spray for control of Saltcedar trees prior to leaves dropping. T-P enterprises will spray these trees next year when trees have leafed out and are actively growing.

Sincerely,

Lynn Smitherman T-P Enterprises, Inc. 719-291-4460 cell

T-P Enterprises, InC.

7340 Utah Lane Colorado Springs, CO. 80923

719-447-9180

SOLD TO: Kiewit Infrastructures CO. 3527 Wabash Colorado Springs, CO. 80906 INVOICE NUMBER INVOICE DATE Cotober 31, 2017 TERMS Net 30

QUANTITY		DESCRIPTION	UNIT PRICE	AMOUNT
	Kiewit Pit			
1.000	LS thistle herbicide control		400.00	400.00
			SUBTOTAL	400.00
MAKE ALL CHECKS PAYABLE TO: T-P Enterprises, Inc. 5055 East 39th Ave.		\$400.00 PAY THIS AMOUNT		

THANK YOU FOR YOUR BUSINESS!

Denver, CO. 80207

INVOICE