

**STATE OF  
COLORADO****Ebert - DNR, Jared <jared.ebert@state.co.us>**

---

**Slope Repair areas, Debetz Pit, M-1977-283.**

4 messages

---

**Ebert - DNR, Jared <jared.ebert@state.co.us>**  
To: Kurt Carlson <KCarlson@adcogov.org>

Thu, Dec 21, 2017 at 2:37 PM

Hello Kurt, I know you are out for the Holidays. When you are back in the office could you please shoot me the photos you took of the slope repair areas. Looking at TR2, it appears only certain areas were designated to be re-graded and stabilized and the remainder of the slopes were to remain "as is". When we were out in the field, it did not appear the areas designated for repair on the west side of the pond had been repaired but it was difficult to tell with the vegetation established along the slope.

Thanks,

Jared

--

Jared Ebert

Environmental Protection Specialist III

**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

P [303.866.3567](tel:303.866.3567) ext. 8120 | F [303.832.8106](tel:303.832.8106) |

1313 Sherman St., Room 215, Denver, CO 80203

[jared.ebert@state.co.us](mailto:jared.ebert@state.co.us) | [mining.state.co.us](http://mining.state.co.us)

---

**Kurt Carlson <KCarlson@adcogov.org>**  
To: "Ebert - DNR, Jared" <jared.ebert@state.co.us>

Tue, Jan 2, 2018 at 9:20 AM

Jared,

Here are the photos that you requested of the work we did in April of 2015 to stabilize the banks on the southern shoreline based on a recommendation from Tyler during an inspection in 2014.


Let me know if you need anything else.

Kurt

**From:** Ebert - DNR, Jared [mailto:[jared.ebert@state.co.us](mailto:jared.ebert@state.co.us)]  
**Sent:** Thursday, December 21, 2017 2:38 PM  
**To:** Kurt Carlson  
**Subject:** Slope Repair areas, Debetz Pit, M-1977-283.

[Quoted text hidden]

---

 **Binder1.pdf**  
15285K

---

**Ebert - DNR, Jared** <[jared.ebert@state.co.us](mailto:jared.ebert@state.co.us)>  
To: Kurt Carlson <[KCarlson@adcogov.org](mailto:KCarlson@adcogov.org)>

Wed, Jan 3, 2018 at 6:50 AM

Thank you Kurt,

So the areas designated for repair on the west side have not been repaired yet, correct? It did not appear so when i was out there.

Thanks,

Jared

[Quoted text hidden]

---

**Kurt Carlson** <[KCarlson@adcogov.org](mailto:KCarlson@adcogov.org)>  
To: "Ebert - DNR, Jared" <[jared.ebert@state.co.us](mailto:jared.ebert@state.co.us)>

Wed, Jan 3, 2018 at 9:02 AM

That is correct. We've been unable to do much work along the west shoreline due to the Golf Course infrastructure / conflicts. Dee Ann (golf course superintendent) has been using their aeration plugs to create a better slope in some of the areas where erosion has occurred and has created more vertical slopes than 3:1.. There have been some improvements in some areas but others have issues with the toe of slope sloughing a bit into the water.



**Kurt Carlson, MAS**

Regional Park Manager, Parks and Open Space

**ADAMS COUNTY, COLORADO**

9755 Henderson Road

Brighton, CO 80601

[kcarlson@adcogov.org](mailto:kcarlson@adcogov.org)

O: 303.637.8013 | F: 303.637.8015



Please consider the environment before printing this email

*This message is intended for use of the addressee and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any use or dissemination of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately by reply and delete this message from your system.*

---

**From:** Ebert - DNR, Jared [mailto:[jared.ebert@state.co.us](mailto:jared.ebert@state.co.us)]  
**Sent:** Wednesday, January 3, 2018 6:51 AM  
**To:** Kurt Carlson  
**Subject:** Re: Slope Repair areas, Debetz Pit, M-1977-283.

[Quoted text hidden]

---



**image001.jpg**  
9K



































