



**COLORADO**

**Division of Reclamation,  
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

May 1, 2018

Caleb Bolander  
Gold Tamers, LLC  
P.O. Box 1447  
Fairplay, CO 80440

**RE: Destiny Pit; DRMS File No. M-2009-056; Receipt of Corrective Action  
Documentation**

Dear Mr. Bolander,

The Division received your above referenced response to the Compliance Problems cited in the Division's report of the inspection that was conducted on December 8, 2017. The status of the corrective actions in regard to the cited problems are as follows:

**Compliance Problem 1: Failure to post a permit sign and delineate the boundary of affected lands.**

This problem is considered to be resolved as a result of the submittal of photographs of the permit sign and boundary markers.

**Compliance Problem 2: Land has been affected outside of the approved permit boundary.**

This problem is considered to be resolved as a result of the submittal of photographs showing the trailers and portable restroom have been relocated to the interior of the mine site.

If you have any questions, please contact me at (303)866-3567 x8116.

Sincerely,

Michael A. Cunningham  
Environmental Protection Specialist

CC: Wally Erickson, DRMS

