

April 27, 2018

Mr. Peter Hays Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO 80203

RE: Greeley 35th Ave, M-1977-036, Follow-up to inspection dated March 28, 2018

Dear Mr. Hays:

The following is the status of the remaining outstanding items on the inspection report:

CORRECTIVE ACTIONS: The Operator shall, at the entrance of the mine site, post a sign which shall be clearly visible from the access road. The operator shall submit photo documentation that a proper sign has been posted by the corrective action date.

RESPONSE: Please find photo attached showing the sign is attached to the fence at the entrance.

Please let me know if anything additional is needed.

Julie Mikulas

Sincerely,

Julie Mikulas

Regional Land Manager

