



COLORADO

**Division of Reclamation,
Mining and Safety**

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

May 21, 2018

Edwin Olivares
GCC Rio Grande, Inc.
3372 Lime Road
Pueblo, CO 81004

**Re: Salt Canyon Project, Permit No. M-1997-064,
Documentation of Corrective Action(s) Received**

Dear Mr. Olivares:

On April 30, 2018 the Division of Reclamation, Mining and Safety received your response via email, regarding the Problem identified during the March 28, 2018 inspection conducted at the Salt Canyon Project and cited in the inspection report dated April 5, 2018. The Division has changed the status of the Corrective Action associated with the following cited Problem to be resolved:

Problem/Possible Violation: The affected area boundary markers are missing on all but the east side of the affected area. This is a problem for failure to maintain boundary markers around the affected area as required by Section 3.1.12(2) of the rule.

The Operator's representative submitted photographs of boundary markers and survey images demonstrating the boundary markers have been placed and the material stockpile in question is within the affected area boundary.

If you have any questions or need further information, please contact me at (303)866-3567 x8169.

Sincerely,

Timothy A. Cazier, P.E.
Environmental Protection Specialist

ec: DRMS file
Joseph Joshua, GCC
Phil Courtney, SLB

