

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

PERMIT INFORMATION

Permit Number: C-1996-084 Mine Name: Lorencito Canyon Mine Operator: New Elk Coal Company, LLC Operator Address: Mr. Louis Head	County: Las Animas Operation Type: Surface Permit Status: Permanent Cessation Ownership: Private			
12250 Highway 12	Operator Representative Present:			
Weston, CO 81091	Nick Mason, Vince Massarotti			
Operator Representative Signature: (Field Issuance Only)				
<u>INSPECTION INFORMATION</u>				

Inspection Start Date: May 22, 2 Inspection Start Time: 12:30 Inspection End Date: Inspection End Time:	2018		Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Cloudy		
Joint Inspection Agency:		Join	Joint Inspection Contacts:		
None					
Post Inspection Agency:		Post Inspection Contacts:			
None					
Inspector(s):	Inspector's Signature: Signature		nature: Signature Date:		
Robert D. Zuber, P.E.	Phot D. ZL				
			5/23/2018		

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

NA - Air Resource Protection R - Roads

Y - Availability of Records R - Reclamation Success

NA - Backfill & Grading Y - Revegetation

R - Excess Spoil and Dev. Waste NA - Subsidence

NA - Explosives

Y - Slides and Other Damage

R - Fish & Wildlife

NA - Support Facilities On-site

V Signs and Markovs

R - Hydrologic Balance Y - Signs and Markers

Y - Gen. Compliance With Mine Plan
 Y - Support Facilities Not On-site
 Y - Special Categories Of Mining

NA - Processing Waste Y - Topsoil

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on May 22, 2018. The weather was partly cloudy and then became windy and rainy at end of inspection. The ground was dry. Nick Mason and Vince Massarotti of NECC were present for the inspection.

EXCESS SPOIL and DEVELOPMENT WASTE - Rule 4.09

Placement; Drainage Control; Surface Stabilization:

Fills 7, 8, and 9 were inspected. No large rills or gullies were seen. The vegetation on Fills 7 and 9 are dry for lack of recent rain on the site.

FISH and WILDLIFE – Rule 4.18:

Several elk were seen near the top of Fill 8.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Several ponds were inspected: 6, 7, 8, 9, and 9A. All but Ponds 6 and 9 were dry. None of them were discharging. No problems were identified with embankments or emergency spillways.

Ditch D86 look to be stable and BMPs are functioning.

ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

No problems were seen with roads.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

Rills on the hillside above Pond 6, on the hillside above the pond cleaning dump area, and on the west side of "the knob" need repair, but do not appear to have gotten worse in past months.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Fill 8



Pond 8



BMPs in Ditch D86



Hill above pond cleaning dump area



West end of "the knob"

Number of <u>Partial</u> Inspection this Fiscal Year: 9 Number of <u>Complete</u> Inspections this Fiscal Year: 4



Hill above Pond 6



Fill 7



Fill 7

AVAILABILITY OF RECORDS

PERMIT RECORDS DRMS Permit	Expires 11/7/2022	HYDROLOGIC RECORDS NPDES Permit	CO0048988
Permit Application w/Revisions	yes	NPDES Records	Q3 2015 (terminated monitoring)
Findings Document	RN4 (Jan. 2018)	Stormwater Management Plan	2007
Insurance Certificate	Exp. April 2019	SPCC Plan	n/a
Bond Document	\$927,121.00	MSHA Pond Inspections	n/a
Phased Bond Release	SL2,	-	
Documents/Findings	Findings 4/29/08	State Engineer's Pond Inspection	n/a
Air Emission Permits	Terminated	Quarterly Pond Inspections	* Comment 1
County Special Use Permits	SUP-01-020	Annual Hydrology Reports	Terminated
UG Mining Landowner Notification	n/a	 Ground Water Monitoring 	
Subsidence Monitoring Reports	n/a	 Surface Water Monitoring 	
Subsidence Monitoring Data	n/a	 Spring & Seep Monitoring 	
Rill & Gully Survey	2017 ARR	 Mine Water Discharge Monitoring 	
Vegetation Monitoring Data		Mine Inflow Study	
Specific Variance Approvals	n/a	Water Consumption Records	
Annual Reclamation Reports	2017	Well Permits	201451, 201453- 201476
Midterm Review Documents	MT4 (findings Jan. 2016)		
DRMS/OSM Inspection	Through		
Reports/Enforcement Actions	April 2018	BLASTING RECORDS	
Transfers/Succession of Operator	Executed 2008	Blasting Publication	n/a
Temporary Cessation Notification	n/a	Blasting Records (3 years)	n/a
Reclamation Cost Estimate	RN4, \$877,328	ATFE Explosives Permit	n/a
CERTIFICATIONS		Blasting Variances	n/a
Pond Certifications	Yes, Exhibit 15	Pre-Blast Surveys	n/a
Annual Certifications for	n/a		
Impoundments			
Fill Certifications for Excess Spoil	2003	ADDITIONAL RECORDS	
or Underground Development Waste		(specify)	
 Quarterly Inspections 	Q4 2017	None at this time	
 Compaction Testing 			
 Final Certification 			
Coal Processing Waste Banks	n/a		
Haul Road Certifications	yes		
Access Road Certifications	yes		

Comments

*1 Through Q4 2017. Staff to contact Ron Thompson for newer reports.