

TRANSIT MIX CONCRETE CO.



May 25, 2018

Tim Cazier, Environmental Protection Specialist
State of Colorado Department of Natural Resources
Division of Reclamation, Mining and Safety
1313 Sherman St., Room 215
Denver, CO 80203

RE: Annual Report for Pikeview Quarry, M-1977-211

Dear Mr. Cazier:

Attached (via electronic upload) are the completed 2018 Annual Report form, map, and annual fee for the Pikeview Quarry, M-1977-211. With the submittal of the Annual Report form, map and fee, we believe the annual reporting requirements for M-1977-211 have been met.

Additional information:

Question 15:

The Permit allows the use of crusher fines as a replacement for topsoil.

Question 16:

The topsoil pile is not seeded. Material is added to it annually. The toe of the topsoil pile is stabilized with erosion control material.

Significant reclamation work for this report year includes working on backfilling the large excavation at the base of the slide area.

If you have any questions, please feel free to contact Mr. Bruce Humphries (consultant for TMCC) at 303-854-7499 or hlhumphries2@comcast.net.

Sincerely,

Andre Laroche
Permit Specialist

Attached (via electronic upload):
Annual Report Form and Map
Annual Report Map

cc: Brandon Heser, Transit Mix Concrete Co.