



STATE OF
COLORADO

Ebert - DNR, Jared <jared.ebert@state.co.us>

McAtee Cnstruction Riverside pit M1976056

Environment-Inc <Environment-inc@outdrs.net>

Mon, Jun 18, 2018 at 12:53 PM

To: Jared Ebert <Jared.Ebert@state.co.us>

Cc: Rod Havens <rhavens@simonteam.com>, Jeff Harms <JHarms@simoncontractors.com>

Jared,

As a follow up on my call about the McAtee Constructions Riverside Pit boundary markers corrective action noted in your May 8, 2018 Inspection Report. I apologize for dropping the ball and not keeping you informed of the progress status.

Leibert -McAtee Surveying was contacted to locate the mine corners and have set the southern boundary corners, but have some of the additional corners that need to be marked. I had to search the old files to find the original survey documents and were able to get them copies to work off of the first week of June. I talked to them today, the registered surveyor is gone this week so they will not have anything before the board hearing next week. I will be prepared to explain the holdup to the Board at that time.

Regards,

Steve

Steve O'Brian

Environment, Inc.

7985 Vance Dr., #205A

Arvada, CO 80003

(303) 423-7297

(303) 423-7599 Fax

Environment-inc@outdrs.net

This e-mail is covered by the Electronic Communications Privacy Act. If you have received this communication in error, please delete this message from all media and notify me immediately. Thank you for your cooperation.