



BLM Colorado, Royal Gorge Field Office 43 CFR 3809 Minerals Inspection/Site Visit

General Information

<i>Date</i>	06/14/2018	
<i>Time Onsite</i>	1015	
<i>Project Name</i>	Exploration – Hanson Ore and Picnic Tree Deposits	
<i>Project Location</i>	Tallahassee Creek Area	
<i>Project Status</i>	Reclamation	
<i>Project Type</i>	Notice	
<i>Occupancy Status</i>	None	
<i>Operator</i>	Western Uranium Corp.	
<i>Case No.</i>	COC-74166	
<i>Inspection Purpose</i>	General	
<i>Attendees</i>	Michael Rutter - Operator	
	Tim Cazier - CDRMS	
	Stephanie Carter - BLM	

Inspection Results

In conformance with 43 CFR 3809.420?	Yes
Mining in conformance with Notice/Plan requirements?	Yes
Reclamation in conformance with Notice and/or Plan requirements?	Yes - ongoing
Hazardous materials/waste onsite?	No
Instructions to Operator	<ul style="list-style-type: none">• Continue removal of silt fence, snow fence, buckets, wood, waddles, wire, etc. at drill pads• Treat thistle at drill pads where it is the dominant weed• Abandon piezometers in accordance with State of Colorado requirements
Date inspection shared with CDRMS/Operator	06/19/2018

Inspection Comments

- Hnd006
 - o Piezometer
 - o Need to abandon (Tim is checking on this process with State Engineer's Office)
 - o Pull waddles
 - o Pad looks good



BLM Colorado, Royal Gorge Field Office

43 CFR 3809 Minerals Inspection/Site Visit

- Hnd003
 - o Pad looks good
 - o Piezometer
 - o Need to abandon
- MW-27-292, 293, 294
 - o All monitoring wells may be retained. If retained, DRMS will keep bond for them.
 - o Field monitoring parameters may be conducted at these on a quarterly basis throughout the year
 - o Pad looks good, except for some thistle infiltration
- MW-27-290, 291
 - o Pad looks good, except for some bind weed (although this is pervasive along the roadway)
 - o Monitoring wells
- MWC-109
 - o Pad looks good
 - o Monitoring well
 - o Need to pick up wood and wire
 - o Note – Drainage nearby has water
- Hndd011
 - o This is a piezometer
 - o Pad looks good
 - o Need to abandon
 - o Need to remove silt fence, snow fence, etc.
- Hndd010
 - o This boring is located on BLM surface
 - o Pad looks good
 - o This is a piezometer that needs to be abandoned
 - o Pull up silt fence, snow fence, etc.
 - o Thistle needs to be treated
- Hndd009 - will check at final release. Couldn't locate at time of the inspection.
- Not looked at during inspection:
 - o MW-27-287
 - o MWC-21-219
 - o MWC-21-210
 - o MWC-21-202
 - o MWC-21-216
 - o Hndd002
 - o Hndd001
 - o MWC-21-150
 - o Hndd004
- Western Uranium Corp. plans moving forward
 - o Keep the 3 holes proposed, but not yet drilled, bonded
 - o All piezometers to be abandoned (including the one on BLM)
 - o Some of the monitoring wells may be abandoned and/or retained for monitoring – need to check
- General
 - o No NI 43-101 for this site, just the Sunday complex
 - o No monitoring or other activities taking place currently



BLM Colorado, Royal Gorge Field Office 43 CFR 3809 Minerals Inspection/Site Visit

Photo Summary





BLM Colorado, Royal Gorge Field Office
43 CFR 3809 Minerals Inspection/Site Visit





BLM Colorado, Royal Gorge Field Office
43 CFR 3809 Minerals Inspection/Site Visit





BLM Colorado, Royal Gorge Field Office
43 CFR 3809 Minerals Inspection/Site Visit





BLM Colorado, Royal Gorge Field Office
43 CFR 3809 Minerals Inspection/Site Visit



