

## TRAPPER MINING INC.

P.O. Box 187

Craig, Colorado 81626

(970) 824-4401

July 23, 2018

Mr. Brock Bowles Environmental Protection Specialist Colorado Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO 80203

## Re: Trapper Mining Inc., Permit No. C-1981-010, Technical Revision TR-121 Johnson/Pyeatt Coal Stockpile Responses to DRMS Comments, Adequacy Review 1

Dear Mr. Bowles:

Please accept this letter as our response to the adequacy review letter dated July 11, 2018. Items requiring a response have been copied below, Trapper's comments follow each as applicable.

Revised permit materials have been included as follows: Page; 3-184 Maps; M6 (Sheet 2) and M13A (Sheet 2)

## DRMS Comments July 11, 2018

1. Please update Map M06 (sheet 2 of 3) Bond Worst Case Year 2014 to show the adjusted disturbance boundary for the new coal stockpile.

*Trapper Response: The additional disturbance anticpated with the stockpile construction has been added to map M6 as requested.* 

2. Map M13A (sheet 2 of 3) Facilities was submitted with the application. The stockpile location is identified on the map and labeled as 'proposed'. Please remove the word 'proposed' from the map. This will eliminate confusion after the revision has been approved

Trapper Response: The label has been revised as requested on Map M13A.

3. The text on the submitted page 3-184 states that perimeter ditches and dozer basins will be utilized to contain the drainage. Please include a reference to the typical design you will utilize to construct the perimeter ditch and dozer basin.

Trapper Response: References have been added to page 3-184 as requested.

TR-121 Response Cont. Page 2 of 2

Please contact me if you have any questions regarding the enclosed information.

Sincerely,

Sala Reve

Graham Roberts Environmental Engineer

GCR [M/Permit Revisions/TR-121 Response1 CL.doc]

c File 109.2.3.4 w/o attachments Revisions File