

#### Minerals Plan of Operations Inspection U.S. Department of the Interior Bureau of Land Management Royal Gorge Field Office



The BLM has conducted an inspection of your operations, which concludes whether the documented operations on file with BLM are compliant or noncompliant. Any non-compliance issues are reported in the Additional Actions Necessary section of this inspection.

**Operation Type:** 🖂 3809 w/ occupancy 🗌 3809 w/o occupancy

Date: 08/10/2018	Operation Name: Gold Tamers-Field of Dreams Mine			
Time: 11:24 am	Operator: Gold Tamers			
Weather: Sunny	Case Number: COC73930			
	CDRMS #: M-2009-056			
Attendees	General			
BLM: Amber Sanderson & Sam Marolt	<b>Operation(s) are in compliance with documentation on file</b>			
	$\Box$ Yes $\boxtimes$ No $\Box$ N/A			
<b>Operator(s): Contacted, but not present</b>	<b>Operation</b> (s) and <b>disturbance</b> on-site coincide with the			
	operations and access on file			
Other(s): None	$\Box$ Yes $\boxtimes$ No $\Box$ N/A			

Inspection	Purpose:
------------	----------

□ Pre-Op	perations
----------	-----------

 $\boxtimes$  General  $\square$  Final

 $\Box$  Trespass  $\Box$  C

□ Complaint

Inspection Items	Compliant	Non- Compliant	N/A	
1. Method of Operations				
Drill, Trench/Surface Excavation/Highwall, Underground Excavation	<u> </u>			
a. Drilling			$\boxtimes$	
Pad Construction				
• Mud Pits				
Borehole Abandonment/Monitoring Well Conversion				
$\Box$ Complete $\Box$ Incomplete				
Pad Reclamation				
b. Trenching/Surface Excavation/Highwall		$\boxtimes$		
Trench/Excavation/Highwall Construction		$\boxtimes$		
• Trench/Excavation/Highwall Stability		$\boxtimes$		
Trench/Excavation/Highwall Reclamation			$\boxtimes$	
c. Underground Excavation			$\boxtimes$	
Portal Construction				
Blasting Operations				
Portal Reclamation/Conversion of Entry				
2. Site Conditions				
a. Material/Waste Rock Management		$\boxtimes$		
b. Erosion & Stormwater Control		$\boxtimes$		
c. Man-made Structures			$\boxtimes$	
d. Weed Management		$\boxtimes$		
e. Safety Conditions		$\boxtimes$		
f. Interim Reclamation			$\boxtimes$	

Inspection Items	Compliant	Non- Compliant	N/A	
3. Housekeeping				
a. Container Management		$\boxtimes$		
b. Spills/Leaks Observed		$\boxtimes$		
c. Hazardous Substances/POL Management	$\boxtimes$			
d. General Housekeeping		$\boxtimes$		
4. Access	•			
a. Road Management	$\square$			
b. Berms			$\boxtimes$	
c. Security		$\boxtimes$		
d. Signage	$\boxtimes$			
e. Surface Water Controls		$\boxtimes$		
5. Quality Assurance/Quality Control				
a. Routine Site Conditions Monitoring		$\boxtimes$		
b. Air, Water, Noise, Other Monitoring		$\boxtimes$		
c. Monitoring Reporting		$\boxtimes$		
d. Regulatory Submittals	$\square$			
e. Other Agency/Entity Permits	$\boxtimes$			
7. Final Reclamation			$\boxtimes$	
a. Exploration/Sampling Location				
b. Access Roads/Trails				
c. Grading				
d. Revegetation				
e. Removal of Structures				
f. Free of Trash				

#### Additional Actions Necessary

Non-Compliance Issues to be addressed by Operator

- All non-compliance items identified in the 07/25/2018 inspection have still not been corrected given the designated 15 day compliance period ending on 08/08/18. The site status remains in non-compliance until the items documented in the 07/05/2018 BLM non-compliance order have been corrected and inspected by the AO.
- Stephanie Carter emailed Joe Widdison (mine owner) requesting images of the corrected non-compliance items on 08/08/18. Mr. Widdison stated the company is awaiting approval of a business transaction to acquire the funds for the excavating equipment to correct non-compliance items #8 & #9. He would need to follow up with Matt Donnelly regarding the remaining non-compliant items (#s 4, 6, 7 & 10).

1.b.i. No dirt work has been performed to correct non-compliance item #9 that was included with the 07/05/18 BLM non-compliance order.

1.b.ii. No dirt work has been performed to correct non-compliance item #8 that was included with the 07/05/18 BLM non-compliance order.

2.b. \*No storm water controls are currently in place at the site. This needs to be done in accordance with the applicable storm water management plan and State of Colorado issued permit. It isn't clear the status of these items.

2.d. Operations and interim management require monitoring and treatment of invasive plants (defined as plants that are not part of the original plant community that have the potential to become a dominant species at the site if not controlled).

2.e. Refer to 1.b.i. & 1.b.ii above.

3.a. A majority of the POL containers have been removed from the site to correct non-compliance item #4, however, there are still some containers remaining (Refer to map and images below).

3.b. \*Oil staining in two separate areas along the eastern region. These areas need to be cleaned and all contaminated soils should be disposed of according to the spill contingency plan documented in your mining plan (Refer to map and images below).

3.d. Some of the trash and other mining related materials have been picked up and removed from the site to correct non-compliance item #6, however there is still quite a bit of trash and mining related materials being improperly stored and managed at the site (Refer to map and images below).

4.c. \*Fence corners and some posts have been installed, however, a fence has yet to be placed around the operations.

4.e. Refer to 2b above.

5.a-c. No documentation was provided regarding the non-operational timeframe, which was needed to correct non-compliance item #10 that was included with the 07/05/18 BLM non-compliance order.

5.d-e. A majority of permits are in place. Follow up needed on the following:

- 1. \*Refer to 2b above. A storm water permit and associated storm water management plan will most likely be required by the State of Colorado for this operation.
- 2. Follow-up with MSHA to see what is required for obtaining a site and/or equipment ID number. *This has been addressed and the MSHA ID # is 0505084.*

# ITEMS PRECEDED WITH AN ASTERIK ARE NOT COVERED BELOW AND REQUIRE ACTION ON THE PART OF THE OPERATOR.

#### Final Notes – COMPLIANCE ACTIONS STILL REQUIRED ARE HIGHLIGHTED

Discussions with Matt on 07/25/2018 regarding status of non-compliance items #1-10 that were included with the 07/05/18 BLM non-compliance order:

#4 Matt stated all items were removed. BLM verified and documented PARTIAL compliance with this item, as some POL containers are still improperly stored and managed across the site. Pictures will need to be provided to BLM to finalize compliance status.

#6 Matt stated some trash was removed, but the rest is being removed today. The tires will be removed tomorrow (along with the dump truck). BLM verified and documented PARTIAL compliance with this item. Pictures will need to be provided to BLM to finalize compliance status.

#7 Matt stated item will be removed within the next three days. BLM verified and documented PARTIAL compliance with this item, as efforts have been made to remove the liner, with advertising it for sale. Pictures will need to be provided to BLM to finalize compliance status.

#8 Matt stated item could not be completed as of yet, because they have no equipment available. INCOMPLETE. This item will need to be completed NLT 8/8/18.

#9 Matt stated item could not be completed as of yet, because they have no equipment available. INCOMPLETE. This item will need to be completed NLT 8/8/18.

#10 Matt stated item was not available, as no monitoring has taken place that he was aware of. However, the site is not abandoned. BLM verified and documented PARTIAL compliance with this item, as no past records are available, but this item will need to be implemented during this time of non-operation. Documentation of interim monitoring, as outlined in the Plan of Operations and associated documents, will need to be provided to the BLM via email. The first week of monitoring and associated documentation will need to be completed by the operator during the week of 7/29/18 and reported to BLM within 5 days following the end of the monitoring week. This monitoring week/reporting sequence will continue into the future, until which time the operator initiates operations.

## THESE ITEMS REQUIRE IMMEDIATE ACTION ON THE PART OF THE OPERATOR.

Proprietary Information: N/A

Date inspection shared with CDRMS:

Date inspection shared with Operator:

Images

Image 1:



Comment: Camper trailer and porta-potty removed, however housekeeping still in non-compliance (e.g. old grill and dumped over garbage can)

## Image 2:



Comment: Area where generators, batteries and propane tanks were concentrated (Non-compliance item #3 & #5)





Comment: POL containers at the site (Non-compliance item #4)

# Image 4:





Comment: Trash and other mining related materials not properly managed or stored (Non-compliance item #6)

### Image 5:



## Image 6:



Comment: Oil spills that need to be cleaned and disposed of according to the spill contingency plan on file.



Comment: SW Stockpile still remains outside of authorized operational boundary (Non-compliance item #8)

Image 8:



## Comment: NW Stockpile still remains outside of authorized operational boundary (Non-compliance item #8)

# Image 9:



Comment: Stockpiles along the NE trench still remain < 1 foot from the trench bank and contain steep slopes (Non-compliance item #9)

# Image 10:







Figure 1: Map of Non-compliance items documented in the 08/10/18. Reference the 07/05/18 BLM Non-compliance order for specific item details.