

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

PERMIT INFORMATION

Permit Number: C-1996-084 Mine Name: Lorencito Canyon Mine Operator: New Elk Coal Company, LLC Operator Address: Mr. Louis Head 12250 Highway 12 Weston, CO 81091 **County:** Las Animas **Operation Type:** Surface **Permit Status:** Permanent Cessation **Ownership:** Private

Operator Representative Present:

Nick Mason and others

Operator Representative Signature: (Field Issuance Only)

INSPECTION INFORMATION

Inspection Start Date: August 22, 2018 Inspection Start Time: 14:00 Inspection End Date: August 23, 2018 Inspection End Time: 10:50			Inspection Type: Coal Comp Inspection Reason: Normal I Weather: Cloudy	·
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspecto	r's Sig	gnature:	Signature Date:
Robert D. Zuber, P.E.	Phet	D.	21-	
				8/24/2018

Inspection Topic Summary

NOTE: Y=Inspected N=	=Not Inspected	R=Comments Noted	V=Violation Issued	NA=Not Applicable
NA - Air Resource Pr	otection		R - Roads	
Y - Availability of Re	cords		R - Reclamation	on Success
NA - Backfill & Grad	ing		Y - Revegetati	on
R - Excess Spoil and	Dev. Waste		NA - Subsiden	ce
NA - Explosives			Y - Slides and	Other Damage
R - Fish & Wildlife			NA - Support l	Facilities On-site
R - Hydrologic Balan	ce		Y - Signs and I	Markers
Y - Gen. Compliance	With Mine P	lan	Y - Support Fa	cilities Not On-site
N - Other			• •	tegories Of Mining
NA - Processing Wast	te		Y - Topsoil	c c

COMMENTS

A complete inspection was conducted by Rob Zuber of DRMS on August 22 and 23, 2018 (only records check on the 22nd). The weather was partly cloudy. The ground was mostly dry. Nick Mason, Bill Massarotti, and Vince Massarotti of NECC were present for the inspection.

EXCESS SPOIL and DEVELOPMENT WASTE – Rule 4.09 Placement; Drainage Control; Surface Stabilization:

Fills 7, 8, and 9 were inspected. No large rills or gullies were seen. The vegetation on Fills 7 and 9 are still relatively dry.

FISH and WILDLIFE – Rule 4.18:

Elk were heard bugling, but none were seen.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

All ponds were inspected: 5, 6, 7, 8, 9, and 9A. None were completely dry, but none of them were discharging. No problems were identified with embankments, spillways, or other features of the ponds.

No problems were found with ditches. In particular, the following ditches (at least significant segments of them) were inspected closely: D5, D9, D73, and D86. The use of branches for erosion control appears to be working well in Ditches D9 and D73.

Culverts C3, C4, and C21 were all clear or mostly clear, and no maintenance is needed at this time. Culvert C20 is shown on the map of ditches and culverts (Map 2.05.3-7) but no longer exists.

Number of Partial Inspection this Fiscal Year: 1

Number of Complete Inspections this Fiscal Year: 1

ROADS – Rule 4.03

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

No problems were seen with roads.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

The area below (and south of) Culvert C5 is in good shape with significant green vegetation. BA-3 is in good shape (viewed from across the creek). The hill known as "the knob" looked to be stable, with no large rills or gullies.

There are many rills and bare spots on the hillside above Pond 6 and on the hillside above the pond cleaning dump area. The rill next to Pond 7 appears to be healing well, and the branches placed in this large rill appear to be helping considerably.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

PHOTOGRAPHS



Fill 7



Sump at upper end of Culvert C4



Ditch D73, looking downstream (west)



Area south of Culvert C5



Branches for erosion control in Ditch D73 (top photo) and Ditch D9 (bottom)



Hill above Pond 6



Fill 7 in background and erosion control branches near middle of photo





Number of <u>Partial</u> Inspection this Fiscal Year: 1 Number of <u>Complete</u> Inspections this Fiscal Year: 1 RDZ

AVAILABILITY OF RECORDS

PERMIT RECORDS DRMS Permit	Expires 11/7/2022	HYDROLOGIC RECORDS NPDES Permit	CO0048988, Expires
Permit Application w/Revisions	yes	NPDES Records	12/31/2020 Q3 2015 (terminated
Findings Document	RN4 (Jan. 2018)	Stormwater Management Plan	monitoring) 2007
Insurance Certificate	Exp. April 2019	SPCC Plan	n/a
Bond Document	\$927,121.00	MSHA Pond Inspections	n/a
Phased Bond Release	SL2,	ľ	
Documents/Findings	Findings 4/29/08	State Engineer's Pond Inspection	n/a
Air Emission Permits	Terminated	Quarterly Pond Inspections	* Comment 1
County Special Use Permits	SUP-01-020	Annual Hydrology Reports	Terminated
UG Mining Landowner Notification	n/a	• Ground Water Monitoring	
Subsidence Monitoring Reports	n/a	• Surface Water Monitoring	
Subsidence Monitoring Data	n/a	• Spring & Seep Monitoring	
Rill & Gully Survey	2017 ARR	Mine Water Discharge Monitoring	
Vegetation Monitoring Data	·	• Mine Inflow Study	
Specific Variance Approvals	n/a	• Water Consumption Records	
Annual Reclamation Reports	2017	I	201451, 201453-
Ĩ		Well Permits	201476
Midterm Review Documents	MT4 (findings		
	Jan. 2016)		
DRMS/OSM Inspection	Through	BLASTING RECORDS	
Reports/Enforcement Actions Transfers/Succession of Operator	July 2018 Executed 2008	Blasting Publication	n /a
Temporary Cessation Notification	n/a	Blasting Records (3 years)	n/a n/a
Reclamation Cost Estimate	RN4, \$877,328	ATFE Explosives Permit	n/a
CERTIFICATIONS	Μη4, φ077,520	Blasting Variances	n/a
Pond Certifications	Yes, Exhibit 15	Pre-Blast Surveys	n/a
Annual Certifications for	n/a	Tie-Diast Surveys	11/ a
Impoundments	11/ d		
Fill Certifications for Excess Spoil or Underground Development Waste	2003	ADDITIONAL RECORDS (specify)	
Quarterly Inspections	Q1 2018	None at this time	
Compaction Testing	X1 2010		
Final Certification			
	n /a		
Coal Processing Waste Banks Haul Road Certifications	n/a		
Access Road Certifications	yes		
ACCESS ROAD CERTIfications	yes		

Comments

*1 Through Q1 2018. Staff to contact Ron Thompson for newer reports.