

September 12, 2018

Division of Reclamation, Mining & Safety  
1313 Sherman Street, Room 215  
Denver, CO 80203



Re: Permit No. M-1997-014 – Deer Creek Quarry - 112c Annual Report

Ladies and Gentlemen:

This letter is submitted by upload as “Additional Information” in response to items on the Division’s on-line annual report form for permit year ended September 12, 2018.

Activity under this permit continues intermittently. There were no new areas of disturbance during the report year ended September 12, 2018, nor did any reclamation activity occur during that period.

Deer Creek Quarry was originally permitted under Permit No. M-1979-214HR. Per documents included with the original permit application, the quarry had been in existence since 1970. On June 16, 1997, Deer Creek Quarry Permit No. M-1997-014 was approved and issued, replacing the original permit. Annual reports prior to the issuance of M-1997-014 cannot be located.

In 1998, Aggregate Industries (formerly CAMAS Colorado) acquired the Deer Creek Quarry from previous owner/operators of the land and mine permit. A review of annual reports filed since 1998 provide minimal information and do not include the detailed reporting currently required under the annual report form; therefore, with regard to responses provided on the 2018 annual report form, supplemental information is provided as follows:

**4. Date of last excavation, processing or hauling?** Reported 12/31/17 but an exact date is unknown. Material from Deer Creek Quarry is hauled from time to time via internal transfer to Aggregate Industries’ Morrison Quarry. It is unknown if there are records of such transfers.

**8. Number of acres currently affected:** Response, 45.0 is approximate based upon previous annual reports.

**13. Total Acres in various states of reclamation:**

**Total acres backfilled:** Response, 0.0 as this is unknown.

**Aggregate Industries**

West Central Region, Inc.  
1687 Cole Boulevard, Suite 300  
Golden, CO 80401

Telephone: 303-985-1070

**An Equal Opportunity Employer**

Division of Reclamation, Mining & Safety  
Page Two  
September 12, 2018

**Total acres graded:** Response, 0.0 as this is unknown.

**Total acres seeded with approved mix:** Response, 0.0 as this is an unknown.

**Seed application method:** Reported "NA" as this is unknown.

**Total acres fertilized:** Reported "0" as this is an unknown.

**Fertilizer application method:** Reported "NA" as this is unknown.

**Total acres with topsoil replaced:** Reported 0.0 as this is unknown.

**Topsoil replacement depth:** 0.0 as this is unknown.

**Total acres mulched:** 0.0 as this is unknown

**Mulch application rate:** Reported "0" since this is an unknown.

**Mulch application method:** Reported "NA" as this is unknown.

**15. Adequate topsoil reserved:** Reported "NA" as this is unknown.

**16. Reserved topsoil vegetated/stabilized?** Reported "NA" as this is unknown.

**22. Map.**

The map submitted for the 2003 annual report reflects current areas of disturbance and therefore that is the map being submitted with this report.

If you have any questions regarding the annual report, please contact me at (970) 396-5252.

Very truly yours,



Connie N. Davis  
Land Manager