

Notes:

(7) Mining continued in areas previously disturbed and from stockpiled material on site. An amendment was filed on 11/19/2018 to add new area.

(9) The area around the remaining lake area continues to return to near pre-flood conditions except where water scoured soil and vegetation from the land along the river. An armored outlet was built on the north end of Lake Robert in Early 2016 and worked as designed in 2016 when the river again enter the mine area during high water periods. There has been no flooding since the spring of 2016 so no filling has taken place. No new area was disturbed but approximately 0.23 acres of new lake area was created in the west area.