


4.5 ACRES DISTURBED




TOPOGRAPHY SOURCE: DISTRICT TOPOGRAPHY
FROM EPP AND ASSOCIATES SURVEY DATED
JANUARY 2011.

NOTES:

1. TOPSOIL TO BE APPLIED AFTER SHAPING AND TILTED TO A DEPTH OF 6 INCHES OR MORE (ENDING TOPSOIL TO EXISTING SOIL)
2. FERTILIZER OF NOT LESS THAN 40% NITROGEN AND 40% PHOSPHORUS SHOULD BE APPLIED UNLESS A SOIL ANALYSIS INDICATES ADDITIONAL N/P FOR EACH APPLICATION OF FERTILIZERS SHOULD BE IMMEDIATELY PRIOR TO THE TIME OF SEEDING.
3. TOPSOIL TO BE RESEEDING WITH THE FOLLOWING SEED MIX:

	% OF MIX	PLS PER ACRE
SMOOTH BROWNCRASS	43	13.0
INTERMEDIATE BROWNCRASS	43	20.0
ALFALFA	20	



Staff Report Page 39 of 39

DCS, Inc.
4121 10th Avenue West
Cedar, CO 80612
303-555-8333
303-555-8333
303-555-8333



LEE E. ANDERSEN, INC.
PROFESSIONAL LAND MEASUREMENT

ONE 4th Avenue West
PO Box 470
Ely, MN 55731
TEL 218/335-2222 FAX 218/335-2221

BREEZE BASIN RESOURCES, LLC
FIRENTHRESS PTY
RECLAMATION PLAN[illegible]

Scale 1" = 40'

Project No.	10-12
Date	02/01/201
By	