

1313 Sherman Street, Room 215, Denver, CO 80203 P 303.866.3567 F 303.832.8106 http://mining.state.co.us

## **PERMIT INFORMATION**

Permit Number: C-1996-084 Mine Name: Lorencito Canyon M Operator: New Elk Coal Compan Operator Address:	ine Operation y, LLC Permit St.	County: Las Animas Operation Type: Surface Permit Status: Permanent Cessation Ownership: Private	
Mr. Louis Head 12250 Highway 12 Weston, CO 81091		Representative Present:  V. Massarotti	
Operator Representative Signatu	re: (Field Issuance Only)		
<u>II</u>	SPECTION INFORMA	ATION	
Inspection Start Date: April 23, 2 Inspection Start Time: 13:00 Inspection End Date: April 24, 20 Inspection End Time: 10:00	Inspectio	Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency:	Joint Inspection	n Contacts:	
None			
Post Inspection Agency:	Post Inspection	Post Inspection Contacts:	
None			
Inspector(s):	nspector's Signature: Signature Date:		

Phot D. ZL

4/25/2019

Robert D. Zuber, P.E.

#### **Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

NA - Air Resource Protection Y - Roads

Y - Availability of Records R - Reclamation Success

NA - Backfill & Grading Y - Revegetation

**R** - Excess Spoil and Dev. Waste **NA** - Subsidence

NA - Explosives Y - Slides and Other Damage
R - Fish & Wildlife NA - Support Facilities On-site

R - Hydrologic Balance Y - Signs and Markers

Y - Gen. Compliance With Mine Plan
 Y - Support Facilities Not On-site
 Y - Special Categories Of Mining

NA - Processing Waste Y - Topsoil

### **COMMENTS**

A complete inspection was conducted by Rob Zuber of DRMS on April 23 and 24, 2019 (only records check on the 23rd). The weather was clear and cool.

The ground was very muddy from rain the day before. To avoid damaging roads and for safety reasons, the steeper roads were not traversed. This included all the roads to ponds.

Vince Massarotti and Nick Mason of NECC were present for the inspection.

#### EXCESS SPOIL and DEVELOPMENT WASTE - Rule 4.09

Placement; Drainage Control; Surface Stabilization:

Fills 7, 8, and 9 were inspected. No large rills or gullies were seen. The vegetation on all three fills looks very good.

FISH and WILDLIFE – Rule 4.18:

Approximately 300 elk were seen crossing the Pond 8 dam.

#### HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Most of the ponds were inspected, but only from the hillside above. This included Ponds 6, 7, 8, 9 and 9A (Pond 5 was not inspected). Ponds 6 and 8 contained significant water. The others were nearly dry or dry. None of them were discharging. No problems were identified with embankments, spillways, or other features of the ponds.

The following ditches (at least significant segments of them) were inspected: D2, D3, D9, D15, D73, and D86. No problems were found with ditches. Branches in D9 and D73 are functioning well to prevent erosion.

Culvert C3 was clear of sediment.

#### RECLAMATION SUCCESS - Rule 4.15, Rule 3:

No erosion or other problems were seen with BA-3 (it was viewed from across the creek).

The hill known as "the knob" looked to be generally stable, with no gullies.

The rills on the hillside above Pond 6 have not gotten worse, but should be treated. Vince indicated that he planned to put more branches there in the very near future. Also, more branches will be placed in rills on the hillside above the pond cleaning dump area. The branches in rills southwest of ditch D9 are functioning well.

### **ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.

# **PHOTOGRAPHS**



Ditch D86



**Top of Fill 8** 



Ditch D73



Ditch D9



Fill 7



Fill 9 and Pond 9A



Pond 6 with BA-3 in background (circled)



Hill above Pond 6



Ditch D3



Ditch D2, above D3 confluence

## **AVAILABILITY OF RECORDS**

PERMIT RECORDS DRMS Permit	Expires 11/7/2022	HYDROLOGIC RECORDS NPDES Permit	CO0048988, Expires 12/31/2020
Permit Application w/Revisions	yes	NPDES Records	Q3 2015 (terminated monitoring)
Findings Document	RN4 (Jan. 2018)	Stormwater Management Plan	yes
Insurance Certificate	Exp. April 2019	SPCC Plan	n/a
Bond Document	\$927,121.00	MSHA Pond Inspections	n/a
Phased Bond Release	SL2,		
Documents/Findings	Findings 4/29/08	State Engineer's Pond Inspection	n/a
Air Emission Permits	Terminated	Quarterly Pond Inspections	* Comment 1
County Special Use Permits	SUP-01-020	Annual Hydrology Reports	Terminated
UG Mining Landowner Notification	n/a	<ul> <li>Ground Water Monitoring</li> </ul>	
Subsidence Monitoring Reports	n/a	<ul> <li>Surface Water Monitoring</li> </ul>	
Subsidence Monitoring Data	n/a	<ul> <li>Spring &amp; Seep Monitoring</li> </ul>	
Rill & Gully Survey	2018 ARR	<ul> <li>Mine Water Discharge Monitoring</li> </ul>	
Vegetation Monitoring Data		<ul> <li>Mine Inflow Study</li> </ul>	
Specific Variance Approvals	n/a	<ul> <li>Water Consumption Records</li> </ul>	
Annual Reclamation Reports	2018	Well Permits	201451, 201453- 201476
Midterm Review Documents	MT4 (findings Jan. 2016)		
DRMS/OSM Inspection	Through		
Reports/Enforcement Actions	March 2019	BLASTING RECORDS	
Transfers/Succession of Operator	Executed 2008	Blasting Publication	n/a
Temporary Cessation Notification	n/a	Blasting Records (3 years)	n/a
Reclamation Cost Estimate	RN4, \$877,328	ATFE Explosives Permit	n/a
CERTIFICATIONS		Blasting Variances	n/a
Pond Certifications	Yes, Exhibit 15	Pre-Blast Surveys	n/a
Annual Certifications for Impoundments	n/a		
Fill Certifications for Excess Spoil or Underground Development Waste	2003	ADDITIONAL RECORDS (specify)	
<ul> <li>Quarterly Inspections</li> </ul>	* Comment 1	None at this time	
Compaction Testing	n/a		
Final Certification	n/a		
Coal Processing Waste Banks	n/a		
Haul Road Certifications	yes		
Access Road Certifications	yes		

#### **Comments**

\*1 Through Q4 2018. Staff to contact Ron Thompson for newer report.