

Notes:

7. Approximately 1.58 acres was stripped and partially mined in 2019. The total disturbance at the mine is 25.73 acres \pm . Mining continues on areas previously disturbed by working into area previously stripped. (tan) and making the mine deeper. The southern and the western parts of the mining face have been temporarily sloped over the last 2 years to a rate that varies from 2:1 to 3:1.

8. We continued to remove material from area previously disturbed or from stockpiles as the market for material dictated. Stripping above the working face on the west side was done in 2015 (brown).

9. An additional 10-12 acres or more may be stripped on the east and south side of the mined area and in previously stripped areas over the next year. Topsoil from when a new area is stripped will be stockpiled along the western mine perimeter.

12. No reclamation is required at this time as mining has not reached the areas adjacent to the mine boundary.

19. Current Bond Amount \$60,500.00. Division reviewed the bond amount on 03/01/2017 when the mine was last inspected and determined it was adequate at that.