

Notes:

9. Mining continued in the dry creek channel that was disturbed in years past (brown).

10. We continued to place backfill material along the south side of the mined area west of West Bijou Creek (tan). Some of the graded slopes along the east side of West Bijou Creek were partially destroyed in the highwater event in 2014 (orange). Some sloping survived from previous years (green) and no other reclamation is required at this time. Approval of importing inert materials to back fill the old mine area was issued on 10 May 2019.

15. As noted in the Mining and Reclamation Plans there is no topsoil to salvage from the mining area.

19. The bond was evaluated by the Division in May 2019 and found to be adequate to complete reclamation.

22. Please refer to the 2019 Annual Report Map for location of the areas of disturbance in the mine.