



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

October 28, 2019

Don Flickinger
Indian Creek Mining Corp
PO Box 350
Kodiak, AK 99615

RE: Proffit Mine; DRMS File No. M-1991-054; Receipt of Corrective Action
Documentation

Dear Mr. Flickinger,

The Division received your above referenced response in regard to the Compliance Problem cited in the report of the inspection conducted on August 15, 2019. The status of the corrective actions regarding these problems are as follows:

Compliance Problem 1: A fuel spill has occurred at the site which has impacted soils, surface water or groundwater.

This problem is considered **abated** as a result of the Operator's submittal of:

- 1.) A description of how the spill was cleaned up containing at a minimum - the appropriate maps, volumes removed, sample locations, analytical data, and photo documentation.
- 2.) Evidence in the form of a receipt that the contaminated soil was disposed of by an approved method (such as sent to an approved landfill, land farming, recycling center, etc.).

If you have any questions, please contact me at (303)866-3567 ext 8180

Sincerely,

Stephanie Mitchell
Environmental Protection Specialist



