MATT COLLINS Central City Consolidated Mining Co. 1508 Ridge Rd. Nederland, CO 80466 (303)570-6269

VIA EMAIL

October 25, 2019

Mr. Jared Ebert Division of Reclamation, Mining and Safety 1313 Sherman St., Room 215 Denver, CO 80203

RE: M1990-041, Inspection 9/16/19, Corrective actions

Dear Mr. Ebert,

In regards to the Problem noted on your Inspection Report of 9/16/19 (affected area boundary markers are missing), Central City Consolidated Mining Co. hereby submits the following corrective action information:

Central City Consolidated Mining Co., via its contractor Black Fox Mining LLC has placed markers at the appropriate boundary corners of the Bates-Hunter mine permit area. These markers are 5-foot long rebar bolts embedded at least 1-foot into the earth and flagged with orange ribbon, or 60d nails with pink whiskers (see photos). The placement of these markers is provided in the attached, highlighted permit map.

We hope this action is sufficient to mitigate the problem. If the Division has additional concerns, please do not hesitate to contact us.

Sincerely,

Matt Collins, P.E.

Cc: Darrell Otten

Enc: Permit Boundary Map - Highlighted

Mr. Jared Ebert Division of Reclamation, Mining and Safety M1990-041: Corrective Actions – Permit Boundary 10/25/2019 Page 1 of 2

Photo 1 - Boundary Marker #2



Photo 2 - Boundary Marker #3



Photo 5 - Boundary Marker #4



Photo 6 - Boundary Marker #6







Photo 7 - Boundary Marker #8



Photo 8 - Boundary Marker #9



Mr. Jared Ebert Division of Reclamation, Mining and Safety M1990-041: Corrective Actions – Permit Boundary

Photo 9 - Boundary Marker #7



10/25/2019 Page 2 of 2

