



STATE OF
COLORADO

Zuber - DNR, Rob <rob.zuber@state.co.us>

Bowie #2 report

3 messages

Zuber - DNR, Rob <rob.zuber@state.co.us>

Tue, Oct 29, 2019 at 12:41 PM

To: Basil Bear <basilbear@wolverinefuels.com>, Tamme Bishop <tamme.jestover@bresnan.net>

Hello. Sorry we missed you last week, Basil. Attached is the inspection report for Bowie #2.

Rob

Rob Zuber, P.E.
Environmental Protection Specialist II
Coal Regulatory Program



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567, extension 8113 | F 303.832.8106
1313 Sherman Street, Room 215, Denver, CO 80203
rob.zuber@state.co.us | <http://mining.state.co.us>



INSP-REPORTC_C1996083_RDZ_10292019121313.pdf
1330K

Tamme Bishop <tamme.jestover@bresnan.net>

Tue, Oct 29, 2019 at 1:48 PM

To: "Zuber - DNR, Rob" <rob.zuber@state.co.us>, Basil Bear <basilbear@wolverinefuels.com>

Hi Rob. What is the reasoning behind moving the coal fines under the conveyor to a gob pile right now?

Tamme Bishop, P.E.
JE Stover & Associates, Inc.
2352 N. 7th Street, Unit B
Grand Junction, CO 81501
970-245-4101

[Quoted text hidden]



Virus-free. www.avg.com

Zuber - DNR, Rob <rob.zuber@state.co.us>

Tue, Oct 29, 2019 at 1:59 PM

To: Tamme Bishop <tamme.jestover@bresnan.net>
Cc: Basil Bear <basilbear@wolverinefuels.com>

Right now the only answer I have is precedent. OSM told another operator to do that. I will look at the rules to give you more information in the next few days.

Rob

Rob Zuber, P.E.
Environmental Protection Specialist II
Coal Regulatory Program



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567, extension 8113 | F 303.832.8106
1313 Sherman Street, Room 215, Denver, CO 80203
rob.zuber@state.co.us | <http://mining.state.co.us>

[Quoted text hidden]