

November 12, 2019

Chris Pyles Gillette Sand and Gravel, Inc. 20575 Hwy 24 Woodland Park, CO 80863

RE: Receipt of Corrective Action Documentation Gillette Pit, Permit File No. M-1992-009

Dear Mr. Pyles,

On November 8, 2019, the Division of Reclamation, Mining and Safety (Division/DRMS) received your corrective action documentation regarding the Compliance Problems identified in the October 4, 2019 inspection report of the Gillette Pit. The corrective action documentation shows the Northern Pit exposed groundwater pond has been backfilled and a detention basin with hay bale check dams has been constructed in the Southern Pit to control off-site sedimentation. **Given this, Compliance Problems #1 and #2 have been resolved.**

If you need additional information or have any questions, please contact me at Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, by telephone at **303-866-3567 x8132**, or by email at <u>elliott.russell@state.co.us</u>.

Sincerely,

Elliott R. Russell Environmental Protection Specialist

ec: Jason Musick with DRMS, <u>jason.musick@state.co.us</u> Brendan Shine with Realtime Aquifer Services, <u>bren.shine@q.com</u>

