

Notes:

Please refer to the 2019 Annual Report Map for location of the areas of disturbance in the mine. We continued to remove material from stockpiles and the partially mined area. No reclamation is required at this time but backfilling is continuing.

8. The area is currently use as a stone storage area until mining resumes. The cross hatched area has been partially reclaimed by placing growth medium along the mined area perimeter.

11. The mine permit area is totally disturbed except for a narrow setback along Siloam Road.

19. The bond is currently set at \$8,300 for disturbance on the entire area. This mine was last inspected on 2/4/2016 and the bond was determined to be adequate by the Division at that time..