


**PERMIT INFORMATION**

<b>Permit Number:</b> C-1981-014 <b>Mine Name:</b> Southfield Mine <b>Operator:</b> Energy Fuels Coal, Inc. <b>Operator Address:</b> Mr John Adams P.O. Box 773457 Steamboat Springs, CO 80477	<b>County:</b> Fremont <b>Operation Type:</b> Underground <b>Permit Status:</b> Revoked <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  None
<b>Operator Representative Signature:</b> (Field Issuance Only)	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> December 23, 2019 <b>Inspection Start Time:</b> 09:00 <b>Inspection End Date:</b> <b>Inspection End Time:</b>		<b>Inspection Type:</b> Coal Complete Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Cloudy	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>  None	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>  None	
<b>Inspector(s):</b>  Zach Trujillo	<b>Inspector's Signature:</b> 		<b>Signature Date:</b>  12/23/19

## Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection  
N - Availability of Records  
N - Backfill & Grading  
N - Excess Spoil and Dev. Waste  
N - Explosives  
N - Fish & Wildlife  
N - Hydrologic Balance  
N - Gen. Compliance With Mine Plan  
N - Other  
N - Processing Waste

N - Roads  
R - Reclamation Success  
N - Revegetation  
N - Subsidence  
N - Slides and Other Damage  
N - Support Facilities On-site  
N - Signs and Markers  
N - Support Facilities Not On-site  
N - Special Categories Of Mining  
N - Topsoil

## COMMENTS

This was a complete inspection of the Southfield Mine conducted by Zach Trujillo of Colorado Division of Reclamation, Mining and Safety (DRMS) on December 23, 2019. The Southfield Mine was an underground mine which the Division has revoked the bond and terminated the permit. Therefore, no mine operator remains. All bond monies available to the Division will be utilized as needed for reclamation and maintenance activities. The weather was cloudy and ground conditions were snowcovered. Temperatures during the inspection were around forty five degrees fahrenheit.

On November 13, 2018, a meeting was held between the Division and The Corley Company. During this meeting, Dr. Corely, president of The Corley Company, informed the Division that it was best that the Division no longer access the site on the lands owned by The Corely Company. Based upon that meeting, the Division no longer inspects that portion of the Southfield Mine.

RECLAMATION SUCCESS - Rule 4.15, Rule 3:

The Road Spur remains stable with good vegetation. Vegetation can be seen established through the snow cover. The two track was snow covered but noticeable vegetation was observed.

The reclaimed substation pad was snow covered but vegetation was visible. Tracks from an ATV or other small vehicle was observed at the reclaimed access road to the pad. It appears that this area is being used to access adjacent land.



Road spur.

## **ENFORCEMENT ACTIONS/COMPLIANCE**

### **Infraction Number: CO2017001**

Inspection Date: May 15, 2017

Date Issued: July 10, 2017

Primary Topic: Gen. Compliance With Mine Plan

Secondary Topic: Administrative

Tertiary Topic:

Description: Failure to maintain minimum requirements for legal compliance. Energy Fuels Coal Inc. was voluntarily dissolved in December 2016.

Abatement #: 1

Abatement Due Date: 8/18/2017

Abatement Due Extended Date:

Abatement Date: 9/13/2018

Abatement Description: Reinstate Energy Fuels Coal, Inc. or provide the Division all necessary information for the transfer, assignment or sale of Permit Rights per Rule 2.08.6.

### **Infraction Number: CO2017002**

Inspection Date: May 15, 2017

Date Issued: July 10, 2017

Primary Topic: Gen. Compliance With Mine Plan

Secondary Topic: Administrative

Tertiary Topic:

Description: Failure to maintain legal right of entry.

Abatement #: 1

Abatement Due Date: 8/18/2017

Abatement Due Extended Date:

Abatement Date: 9/13/2017

Abatement Description: Reacquire legal right of entry.

### **Infraction Number: CO2017003**

Inspection Date: May 15, 2017

Date Issued: July 10, 2017

Primary Topic: Signs & Markers

Secondary Topic:

Tertiary Topic:

Description: Failure to maintain mine and permit identification signs.

Abatement #: 1

Abatement Due Date: 8/18/2017

Abatement Due Extended Date:

Abatement Date: 9/13/2017

Abatement Description: Reinstall mine and permit identification signs.

### **Infraction Number: CV2017001**

Inspection Date: May 15, 2017

Date Issued: May 23, 2017

Primary Topic: Gen. Compliance With Mine Plan

Secondary Topic: Administrative

Tertiary Topic:

Description: Failure to maintain minimum requirements for legal compliance. Energy Fuels Coal Inc. was voluntarily dissolved in December 2016.

Abatement #: 1

Abatement Due Date: 6/30/2017

Abatement Due Extended Date:  
Abatement Date: 9/13/2017  
Abatement Description: Reinstate Energy Fuels Coal, Inc. or provide the Division all necessary information for the transfer, assignment or sale of Permit Rights per Rule 2.08.6.

**Infraction Number: CV2017002**

Inspection Date: May 15, 2017  
Date Issued: May 23, 2017  
Primary Topic: Gen. Compliance With Mine Plan  
Secondary Topic: Administrative  
Tertiary Topic:  
Description: Failure to maintain legal right of entry.  
Abatement #: 1  
Abatement Due Date: 6/30/2017  
Abatement Due Extended Date:  
Abatement Date: 9/13/2017  
Abatement Description: Reacquire legal right of entry.

**Infraction Number: CV2017003**

Inspection Date: May 15, 2017  
Date Issued: May 23, 2017  
Primary Topic: Signs & Markers  
Secondary Topic:  
Tertiary Topic:  
Description: Failure to maintain mine and permit identification signs.  
Abatement #: 1  
Abatement Due Date: 6/30/2017  
Abatement Due Extended Date:  
Abatement Date: 9/13/2017  
Abatement Description: Reinstall mine and permit identification signs.