



Phillip Courtney
Land Manager

January 20, 2020

Mr. Eric Scott
Colorado Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

By Electronic Mail

RE: Specification Aggregates Quarry M-1974-004

Dear Mr. Scott:

Your inspection report of November 22, 2019 for the permit referenced above requested the following corrective actions:

"All mining related equipment will need to be moved back into the permitted area within 60 days of the date of this inspection report, and proof that this has been done (photos, etc.) submitted to DRMS."

We submit this letter as proof that the corrective actions are completed. All equipment has been moved within the permitted area or removed from site altogether. Attached are several photos to document this action.

Please let me know if you have any questions or need any additional information.

Sincerely,

A handwritten signature in black ink, appearing to read "Phillip J. Courtney".

Phillip J. Courtney
Land Manager

Rocky Mountain Division

1627 Cole Boulevard, Suite 200, Lakewood, CO 80401

t. (720) 612-6232 m. (303) 902-0964 e. phillip.courtney@martinmarietta.com

www.martinmarietta.com



Looking west



View looking south



Looking east



Looking north