



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

January 30, 2020

RE: Burton Pit; DRMS File No. M-1987-013; Receipt of Corrective Action Documentation

Dear Mr. Salazar,

The Division received your above referenced response in regard to the Compliance Problem cited in the report of the inspection conducted on November 7, 2019. The status of the corrective actions regarding these problems are as follows:

Compliance Problem 1: A material stockpile is stored outside of the southern permit boundary

This problem is considered **abated** as a result of the Operator's submittal of:

- 1.) An updated map showing where the stockpile is located within the permit boundary.

If you have any questions, please contact me at (303)866-3567 ext 8180

Sincerely,

Stephanie Mitchell
Environmental Protection Specialist



