DRMS Complaint Intake Tool

By Submitting this form you are requesting an investigation of compliance with DRMS rules.

▼

▼

DRMS Internal Information

Select Permit Type *

Minerals

Permit No List *

M1985112

COMPLAINANT INFORMATION

Date of Complaint

03/11/2020

*Indicates a Required Field

Do you wish to remain anonymous? *

🔵 Yes 💿 No

Your First Name *

Lida

Your Last Name *

Stout

Your Address *

301 Willow Ave

Your City *

Eaton

Your State

CO •



COLORADO

Division of Reclamation, Mining and Safety

Department of Natural Resources

Your Zip Code *

Maximum of 10 digits. (Example) 80202

80615

Email Address *

Enter a valid email address in this field to receive a confirmation e-mail and copy of your Complaint form.

greeleyrealtor@aol.com	
Your Phone Number *	
Used only to follow up. Please enter phone number in	this format: (Example) 123-456-7890
970-396-9926	
Alternate Phone Number	
Used only to follow up. Please enter phone number in	this format: (Example) 123-456-7890
970-384-8583	
Connection to Incident * Select all that apply	
 Land Owner 	Mineral Owner
Nearby Resident	Observed Incident
Other	

DESCRIPTION OF COMPLAINT

(Please be as specific as possible)

Note: Please provide as much detail related to location and issue as possible. Without enough detail, DRMS will not be able to process or investigate the complaint and, therefore, DRMS will have no choice but to discard the complaint.

Location of Concern *

Please provide as much detail as possible. It is important to narrow down the location. If available, please include Township, Range and Section, physical address, or GPS location. You may also upload a pdf map below.

I was informed that I could re-file my earlier complaint against Loloff Construction Company because in the first complaint I did not make it very clear as to when my well actually went dry. I am referring to the general purpose well located on 170 1st Ave, Greeley CO in the Lundgren Subdivision about a mile west of the gravel mining operation of Loloff Construction Company. I am attaching a statement regarding when the well actually went dry and other information as to why I was not informed that the well was dry

Incident County *

Weld County

Is this an ongoing issue(s)?

🖲 Yes 🔵 No

Nature of Complaint *

Select all that apply	
Illegal Mining	Dust
🖉 Ground Water / Water Well Impact	Acid or Toxic Materials/Spills
Surface Water Impact / Stormwater	Property Damage
Management	
Mine Plan Compliance	📃 Waste Management / Dumping
Signs and Markers	🔲 Overburden / Development Waste
Financial Warranty	Backfilling and Grading
Processing Waste / Tailings	Processing Facilities
🔲 Fish / Wildlife	Erosion / Sedimentation
🖉 Off-Site Damage	Roads
Explosives / Blasting	Topsoil
Revegetation	Weeds
Reclamation Plan Compliance	Other

Detailed description of the issue(s) * (?)

Please provide as much detail as possible. It is important to narrow down the issue(s).

This property was rented during the time the well went dry. I was not informed of the problem until the renter left the property. The gravel pit to the east of Lundgren Sub de-watered all the wells in the Lundgren Sub. Owners to the east were supplied with district water by Loloff Construction and to the west they re-drilled the unregistered well of those property owners. Because I was not aware the well was dry until 2017, years after the well ceased pumping water, I did not file a claim until recently. Please

Have you contacted the operator or party conducting the operation? If yes, please provide details. *

Yes No

If known, please provide the name of the operator or party conducting the operation.

Loloff Construction mine dba Broken Arrow Mine

If known, please provide the Permit or NOI Number (ie M-1970-111 or P-1970-111).

Must be entered in the following format: M1970111 or P1970111 (No dashes allowed)

M1985112

Have you contacted any other agencies or local governments related to this issue or issues? If so, please provide details. *

Yes No

ADDITIONAL INFORMATION

Are there supporting photos, maps, or documents you wish to upload? $^{m *}$

💿 Yes 🔵 No

View Attachments in WebLink

Attachments are accepted for informational purposes only. Action by DRMS requires a direct observation by DRMS staff.

What is your preferred method for DRMS to communicate with you throughout the investigation? *

Select all that apply

🕑 Phone 🗹 E-mail 🗹 US Mail

Comments



Submit

STATEMENT OF KAY STOUT

This letter accompanies my addition complaint against Loloff Construction Company regarding the damage caused to my domestic well located at 170 1st Avenue.

I purchased this property in June of 2006. It was service by a domestic well which at that time was 25 foot deep with the water level 5 ft. below the surface. I rented the property continuously until October 2016. The most recent renter was Luis Medrano whose property was adjacent to the south. Mr. Medrano used the property for storage and used the dwelling to house his hired personnel. Neither Medrano nor the anyone living in the house ever informed me that the well had gone dry, however during this time Medrano called me on several occasions to say the sewer was not working. It was pumped twice that year, maybe 2015, but the inhabitant had Medrano call 3 or 4 times about the "sewer" not working which did not make sense to me. In retrospect, I think we had a miscommunication because of the language difference. He most likely was trying to say the pump (well) was not working. In December 2015 I was called because the well was not "working" and I sent Quality Well and Pump to the property. I got a bill for \$297.80 but no report so on March 5 of this year, I called them and asked about that invoice. Their report was that the renter had replaced the pump (without telling me) and the bill was for recharging the pressure tank. Their documentation was that there was only a foot of water at the bottom of the well on that date.

The reason Medrano ceased renting was because the property to the east (182 1st Ave) had been sold to a person who erected a fence along the true property line. The legal description for the property listed the true property lines as well as an ingress/egress easement of some feet onto the 182 1st Ave property. This fence on the property line actually left about 6 feet from my door steps to the fence, effectively cutting off my access to my property.

After the renter left in Oct. 2016 I took steps cure the problem with this fence and eventually I filed a lawsuit and the fence was finally moved to allow for ingress/egress to the property in Aug of 2017. During this time I allowed a niece to use the property for storage in exchange for cleaning up the grounds but she moved items into the house and began "living" there. I protested that she had not rented the house and her response in approximately April of 2017 was that she was not "renting" as it did not have any water in the well and had not had water since she first moved her things there. She told me she had called Quality Well and Pump and in January 2017 and had been told the well was dry.

This was the first I had actually heard of a problem with the well. I realized I would have to re-drill the well and went to the State Division of Water Resources to make sure it was a registered well. I learned that it was the ONLY registered well in the 3 properties of Lundgren Subdivision. I had the registration transferred to my name because I knew when I sold the property I would have to transfer that registration to the new owner.

I continued to allow my niece to stay in the house, not only because she had no place to go, but with the animosity with the neighbor to the east, I felt there needed to be someone there to watch the property.

When the fence was moved in Aug of 2017 I was not successful in evicting my niece until April of 2018. Now I finally had access to my property and I set about rehabilitating it. I decided that I had such extensive repairs to make that I would wait until the end of the rehab process to re-drill the well in case I would need to take out a loan to do so. If I waited until just before the house sold, it would be a short term loan.

It was about this time that I learned the reason the well had gone dry was the gravel pit. I had been told that the pit had been lined and the water would be coming back up, which was another reason I did not re-drill the well right away.

I have attached a statement from the contractor working on the house that he would need water occasionally and was checking the depth and water level of the well, hoping that the water would in fact return. He told me that from time to time that surface water would reach the well after a rainstorm or such but that the well remained approximately 19 feet deep with a foot or two of water at the bottom, which when used, did not return for some length of time. Essentially the well was still dry.

In the fall of 2018 I contacted Quality Well and Pump about re-drilling the well. We had a couple of problems right away. First, although that fence had been moved to the ingress/egress easement lines, it was still too close to the house to allow for the equipment to enter the property, let alone set up to drill so close to the house. Second, we would not be able to get a drill permit to put a full use well in the same location because it was too close to the existing septic tank. And third, Quality Well and Pump told me for months that they were too busy to do the work, at one point mentioning to me that they were re-drilling or drilling numerous wells down in that area west of the gravel pit. It was not until April of 2019 that I finally got the well drilled, having to move it to the south of the original well and pay for additional plumbing to get the water up to the house. I sold the property in May 2019.

I wish that I had monitored and recorded the levels in the existing well but I was foolishly confident that if Loloff Construction re-drilled the well on the Perea property to the east of mine and connected district water to the Hernandez property to the west of mine that they would also be liable for the loss of use of my well between these two. It was my thought that I had a registered water right and that the gravel company had no right to infringe on that right.

This well went dry during the time the property was rented by Medrano and I was not informed of that fact but it went dry in either 2014 or 2015 when the renter was complaining that the "sewer" did not work and actually did replace the pump. Loloff Construction knew that the wells on the properties on both sides of me had been "de-watered" but did not make any attempt to contact me to see whether or not I had the same problem.

I sold the property to Tom Toney, and if it is necessary to inspect the property at this time, I can contact this new owner to see if we can get access to ascertain the true location of both wells. I am not sure if Quality Well and Pump closed in the old well. It was my understanding that closing the old well would be a requirement of drilling the new one.

I am attaching the following information:

An overhead view of Lundgren subdivision showing the Hernandez property (160), my property marked in red and the Perea property (182).

A closer overhead view of Lundren subdivision showing the approximate location of the old well and the approximate location of the new well.

The April 1, 2019 statement for the drilling of the new well.

The April 18, 2019 statement for the plumbing installation for the new well.

The Well Construction and Yield Estimate Report on the new well.

The Pump installation and Production Equipment Test Report on the new well.

The Statement of James Johnson about his personal observation over time on the function of the old well.

Jup Stout

3-11-20

Name

Date



Statement

Date

4/1/2019

Bill To TERRY STOUT

301 WILLOW AVE EATON, CO 80615

				Amount Due	Amount Enc.
• •				\$9,726.96	
Date		Description		Amount	Balance
3/29/2019	INV #2019-561. Du P#23312A	e 04/07/2019. Orig. A	Amount \$9,726.96.	9,726.96	9,726.96
Current	1-30 Days Past Due	31-60 Days Past Due	61-90 Days Past Due	Over 90 Days Past Due	Amount Due
0.00	9,726.96	0.00	0.00	0.00	\$9,726.96

\int	QUALITY WELL AN PO BOX 577	D PUMP			Invoice
	GREELEY, CO 80632		Due Date	Date	Invoice #
Phone # Fax #	9703533118 970-284-6445		4/27/2019	4/18/2019	2019-894
Bill To		0513201	/a		
301 W	STOUT ILLOW AVE I, CO 80615	05			

970-396-9926

Please check box if address is incorrect or has changed, and indicate change(s) on reverse side.

Balance Due

\$0.00

QUALITY WELL AND PUMP

PLEASE DETACH AND RETURN TOP PORTION WITH YOUR PAYMENT.

			P.O. No.	Terms	Project	Rep	
			23312A 170 E	NET 10		KDD	
Qty	Backordered	Item	Desc	ription	Unit Price	Amount	
1 2 2 1 10 6 8	0 0 0	TMU060 TMHS4 TMRCN050 TMU140 10 11-RENTAL MI-10	SHARK BITE REDUCI 3/4" HEAT SHRINK KIT #1 CONDUIT ROMEX CO SHARK BITE MALE AL DOMESTIC SERVICE, MINI - EXCAVATOR P MILEAGE - DOMESTIC Sales Tax	lo, 12, 14 4Wire NNECTOR .50" DAPTER 1" HOURLY RATE BH - HOURLY RATE	35.67 5.98 2.42 23.86 137.50 95.00 2.85 7.01%	35.67 11.96 4.84 23.86 1,375.00 570.00 22.80 260.34	
	*****			Total		\$5,372.00	
				Payments/Cre	dits	-\$5,372.00	
				Balance Due		\$0.00	

The title to the merchandise and personal property covered by this invoice shall remain vested in Quality Well and Pump, LLC until the purchase price is paid in full. Customer agrees to pay a service charge computed at a periodic rate of 1.5% per month (18%APR) applied to all past due amounts after deducting current payments/credits. Page 2

Customer Signature:

(Δ)	PO BOX 577				Invoice
	GREELEY, CO 80632		Due Date	Date	Invoice #
Phone # Fax #	9703533118 970-284-6445		4/27/2019	4/18/2019	2019-894
Bill To		320	(a		
	STOUT ILLOW AVE	0.24			

970-396-9926

Twite

Please check box if address is incorrect or has changed, and indicate change(s) on reverse side.

no 4249 4250 mmo 4570 anno 4250 anno 4250 anno 4266 mmo 4266 anno 4266 anno 4260 anno 4260 4260 4260 4260

OUALITY WELL AND PUMP

New e-mail address? Enter here:

EATON, CO 80615

QUALITY WELL AND PUMP

PLEASE DETACH AND RETURN TOP PORTION WITH YOUR PAYMENT.

cours along series sink state along and state state the state

Balance Due

			P.O. No.	Terms	Project	Rep	
			23312A 170 E	NET 10		KDD	
Qty	Backordered	Item	Descr	iption	Unit Price	Amount	
			INSTALLATION OF NE		М		
			IN NEW WELL UNDER	and the second	an a		
1		TM10FA05S4	FPS TRI .50HP 10GPM		975.20	975.20	
1	0	TM125BTLF	PITLESS ADAPTER BA	KER 1.25" X 5-8"	217.79	217.79	
1	0	TMH2PL22	H2PL FIBER 22		444.38	444.38	
1	0	TM1BAT82FLF	1" X 4.25" BREAK TAN	IK TEE	102.97	102.97	
1	0	TMFSG24060	PRESSURE SWITCH 4	0/60 PSI	33.45	33.45	
1	0	TMBD050	BOILER DRAIN .50"		9.84	9.84	
1	0	TMPG1TNL	PRESSURE GAUGE 0-1	.00 2"	13.58	13.58	
1	0	TMRV05075	RELIEF VALVE .5" SET	@ 75#	17.17	17.17	
1	0	TMFECB0501	FE BOX .50HP 115V		118.01	118.01	
55	0	TM103GPJ5/10	WIRE 10/3 SUB CABLE		1.97	108.35	
150	0	TMUF103G10	WIRE 10/3 UF W/GRD	CABLE	2.05	307.50	
40	0	TM12580	PVC PIPE SCH80 DRO	P PIPE 1.25"	1.82	72.80	
1	0	TMSS670010	CPLG DROP PIPE 1" S	S	12.96	12.96	
130	0	TMWIRAP100	AQUA PEX TUBING 1" FOOT	SHARK BITE PER	2.62	340.60	
1	0	TM637168	BRASS BUSHING 1.25	" X 1"	14.52	14.52	
1	0	TMCV125BE	CHECK VALVE 1.25" N	O-LEAD 80BE 4052E	E 90.60	90.60	
20	0	TM20122-1	AQUA PEX TUBING 3/ FOOT	4" SHARK BITE PER	1.29	25.80	
2	0	TMU134	SHARK BITE MALE AD	APTER 3/4"	12.70	25.40	
2		TM22185	SHARK BITE BALL VALVE 3/4"		36.63	73.26	
1		TMU370	SHARK BITE TEE 3/4"		16.33	16.33	
1		TMU260	SHARK BITE 90DEG E		31.58	31.58	
1	0	and the second se	SHARK BITE 90DEG E		15.44	15.44	

Total

Payments/Credits

Balance Due

The title to the merchandise and personal property covered by this invoice shall remain vested in Quality Well and Pump, LLC until the purchase price is paid in full. Customer agrees to pay a service charge computed at a periodic rate of 1.5% per month (18%APR) applied to all past due amounts after deducting current payments/credits.

Page 1

Customer Signature:

STATEMENT OF JAMES JOHNSON

My name is James Johnson. Between April of 2018 and January of 2019 I was employed to renovate the property located at 170 1st Avenue in Greeley. It was challenging because I had no water to wash my hands, clean my brushes, mix concrete and grout and other things necessary during the job.

The well would pump a few gallons of water if I turned on a tap, but then it would go dry and I would have to wait a few days to get water again. I was told the water level would come back and so from time to time I would drop a line and check the depth and water level of the well. The well was approximately 19 foot deep and I would find a foot or two of water at the bottom.

The well never did provide water as it should during the entire time I worked there.

Johnson Name

Date





	V	VELL CONSTRUC	TION AND VI	ELD ESTIMA	TE REPORT		For	Office Use C	Inly
Form No.									
GWS-31	State of Colorado, Office of the State Engineer 1 1313 Sherman St., Room 821, Denver, CO 80203 303.866.3581								
02/2017	www.water.state.co.us and dwrpermitsonline@state.co.us								
1 Well Permit	Number: 23312	Δ	Receipt N	umber: 369	0447				
	Il Designation:	<u> </u>			0117				
J	Name: TERRY STO								
1	on Street Address		PEELEY COL	80632					
	S Well Location (re				a: 527385 0	Northing: 4	475828		
	Location: <u>NW</u> 1							W - 1 6T	HPM
County: V		<u>, m</u> 174,	Jec., <u>,</u>	1 mp. <u>5</u>		, nunge		·· 🖵 · 🚢	<u> </u>
			tany in a system of the first start		, Lot	-, Block —	, Filii	ng (Unit)	
	face Elevation:		t Date Com	pleted: 03/	08/2019	Drilling Met	hod: ROTARY		
8. Completed	Aquifer Name : /	ALLVUIAL	T	otal Depth:	70 fe		pth Completed		feet
9. Advance No	otification: Was N							en: <u>03/05/2</u>	019
10. Aquifer Ty		One Confining L			Multiple Conf				
(Check on		(Not overlain by	/ Type III)	Type II	(Overlain by T		Type III (the second s
11. Geologic	Log:			-	12. Hole Di	0000-001010-0000-0000-0000-0000-0000-0		n (ft)	To (ft)
Depth	Туре	Grain Size	Color	Water Loc.	8	3/4		0	70
0-2	TOP SOIL								
2-15	COBBLE/SAND	COURSE -1"	BROWN						
15-40	SAND/GRAVEL	COURSE - 1/4	BROWN	XXX	13. Plain Ca	ising			-
40-65	GRAVEL/SAND	COURSE - 1/4	BROWN	XXX	OD (in)	Kind	Wall Size (in)	From (ft)	To (ft)
65-70	SHALE		BLUE/GREY		6 5/8	STEEL	.188	+1	19
					4 1/2	PVC	.250	5	34
					Perforate	ed Casing Sc	reen Slot Size (in): <u>.020</u>	
L	1				OD (in)	Kind	Wall Size (in)	From (ft)	To (ft)
					4 1/2	PVC	.250	34	64
		ļ							
L	ļ						1		
J					14. Filter P			er Placeme	nt:
					Material	GRAVEL	- Type		
					Size	3/8			
					Interval	19-64	Depth		
					16. Groutin	And the second second second second		N 1057 V N	
Demoster	I			1	Material	Amount	Density	Interval	Method PUMPED
Remarks:					CEMENT	8 SKS	1.86	0-19	PUMPED
1									
17 Disinfecti	ion: Type STERILE	INF			Amt. Use	4 5 07			R
	Estimate Data:	INL	Chack br	ov if Tort Dat			umber GWS-39,	Wall Vield 7	Task Dasaut
	Estimate Method:	AIR LIFTED AN	D OVER PUMP	ED		U OH FOHH N	under Gw5-39,	well field	est keport
Static Leve					'ield (gpm) 2-	4			
		03/20/2019	and and a specific sp			1			
	e measured:	03/20/2019		Estimate Le	ngth (hrs) <u>6</u>				
Remarks:									
19. I have read	the statements made	herein and know th	ne contents the	reof, and they	are true to my	knowledge, TI	nis document is sig	ned (or name	entered if
statements is a v	certified in accordan iolation of section 37	ce with Rule 17.4 (of the Water We	ell Construction	Rules, 2 CCR 4	102 2. The filin	ng of a document t	hat contains fa	alse
the State Engine	er considers the entry	of the licensed co	ntractor's name	to be complia	nce with Rule 1	7.4.	of the contractin	g ucense. If f	ling online
								1	
Company Name			Email: kristie@quali	itywellandou	mp.com	Phone w/ar (970)	ea code: 353-3118	License Nu 1461	mber:
	s: 39525 US HWY 8	5. AULT CO 804			mp.com	(770)	555-5110	1401	
and the second se	name if filing onlir			e and Title			and a standard standa	Data	
	Contra Contra	- /		NES, OWNER				Date:	
	hand		CIII(15 50)	nes, OWNER				04/19/201	9
Instantin and a statistic									

1		AND PRODUCTION FOURMENT TEST	DEDORT	For Office Use Only
Form No.		N AND PRODUCTION EQUIPMENT TEST Colorado, Office of the State Engineer	REPORT	
GWS-32		, Room 821, Denver, CO 80203 303.866	3581	
10/2016		te.co.us and dwrpermitsonline@state.co		· ·
4 Well Dermit	Number: 23312A	Receipt Number: 3690447		
and the second		Receipt Number: 3090447		
2. Owner's We	Name: TERRY STOUT			
and the second se	on Street Address: 170 1ST A	VE GREELEY CO 80631		
	cation: Zone 12 Zone		5828 Count	WELD
5. GPS Well LU	cation:	/4, Sec. <u>4</u> Twp. <u>5</u> Nor 1		
Dictorcoc from	Soction Lines:	ft. from \square N or S \square sec. line, and	ft from	For W sec. line
Subdivision:		, Lot,	Block	Filing (Unit)
3834-500				
7. Check Insta	llation Type: 🖌 Initial Pum	p Installation Replacement Pump	Change in Dep	oth Only Repair
8 Dump Data	Type: SUBMERSIBLE	Date Installe	d(mm/dd/www).	4/01/2019
Pump Manufact	turer: FRANKLIN	Pump Model I	No. 10FA05S43W	115
Design GPM: 1	5 at RPM 3450	Pump Model I HP_1/2 Volts_115V	Full Load Am	ps 12
Pump Intake De	epth: 48 Feet, Drop/Co	lumn Pipe Size Inches, 1.25 Kind of 1	Drop Pipe PVC	
		han 50 GPM: Turbine Driver Type:		Other
		Number of Stages:		inches
9. Other Equip		epth ft Monitor Tube Inst		o Depth ft
Flow Meter Mfg			l No.	
		allons, Acre feet Beginning Read		
meter neudouc				
	Courseling Materials	Casacitus	llans Data lastall	odi
		Capacity:gai		
11. Production	n Equipment Test Data:	check box if data is submitted on For	rm Number GWS-3	9 Well Yield Test Report.
	Date			
Total Well Dep	oth:64ft. Time	e: <u>13:00</u>		
Static Level:		e (gpm): 15 ping Level (ft): 10		
Date Measured	<u>1: 04/01/2019</u> Pum	ping Level (ft): <u>10</u>		
			Amt. Used: 4 07	
1	on: Type: STERILENE			
		on Required Prior to Installation? • Yes		fication Given: 03/28/2019
Contraction of the second seco	ality analysis available: 🔲 🗎	/es 🖪 No If yes, please submit wit	h this report.	
15. Remarks:				
			and the second secon	
16. I have read	d the statements made here	in and know the contents thereof, and the	hey are true to my	/ knowledge. This
A 1990 Solid State Club Lange State Math. 2010 11 (1992) 1		ng online) and certified in accordance v		and the second
Rules, 2 CCR 4	02-2. The filing of a docume	ent that contains false statements is a v	iolation of section	37-91-108(1)(e), C.R.S.,
and is punisha	ble by fines up to \$1,000 and	l/or revocation of the contracting licens	e. If filing online	, the State Engineer
considers the	entry of the licensed contrac	tor's name to be compliance with Rule 1	17.4.	
Company Nam	le:	Email:	Phone w/area coo	de: License Number:
			(070) 252 2	
	ITY WELL AND PUMP	kristie@qualitywellandpump.com	(9/0) 353-3	118 1461
QUAL	ITY WELL AND PUMP		(970) 353-3	118 1461
	ITY WELL AND PUMP	39525 US HWY 85, AULT, CC		118 1461
QUAL Mailing Addres	ITY WELL AND PUMP			118 1461 Date:
QUAL Mailing Addres	SS:	39525 US HWY 85, AULT, CC	0 80610	

a stara a