



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

March 19, 2020

Levi Schlosser
Schlosser Incorporated
755 Hwy 385
Burlington, CO 80807

**RE: Receipt of Corrective Action Documentation
Schlosser Pit 1, Permit File No. M-2014-061**

Dear Mr. Schlosser,

On March 19, 2020, the Division of Reclamation, Mining and Safety (Division/DRMS) received your corrective action documentation regarding three of the compliance problems identified in the February 10, 2020 inspection report for the Schlosser Pit 1. The corrective action documentation shows the material blocking the channel of Sandy Creek has been removed, storm water controls have been constructed between Sandy Creek and the mining disturbance, and a new permit sign has been installed. Given this, Compliance Problems #1, #2, and #3 has been resolved. As a reminder, the remaining unresolved compliance problem, Compliance Problem #4, requires the Operator to conduct a survey and replace the affected lands boundary markers in the correct locations and submit proof to the Division on or before April 14, 2020.

If you need additional information or have any questions, please contact me at Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, by telephone at **303-866-3567 x8132**, or by email at elliott.russell@state.co.us.

Sincerely,

Elliott R. Russell
Environmental Protection Specialist

cc: Jason Musick with DRMS, jason.musick@state.co.us

