



March 25, 2020

Cameron Mang  
SEMA Construction, Inc.  
7353 S Eagle St  
Centennial, CO 80112

**Re: Diehl Borrow Pit, Permit No. M-2018-054, Status of Required Corrective Actions**

Mr. Mang:

The Division of Reclamation, Mining and Safety (Division) is providing the following status update on the corrective actions required by the inspection report mailed on March 5, 2020 for the Diehl Borrow Pit, Permit No. M-2018-054:

**INSPECTION TOPIC:** Signs & Markers

**PROBLEM:** The mine identification sign was not posted at the entrance of the mine site. This is a problem for failure to post a mine identification sign as required by Rule 3.1.12(1).

**CORRECTIVE ACTIONS:** The operator shall, at the entrance of the mine site, post a sign which shall be clearly visible from the access road, with a minimum size equaling 187 square inches, such as 11 inches in height by 17 inches in width, with appropriate font size, including the following: the name of the operator and operation name, a statement that a reclamation permit for the operation has been issued by the Colorado Mined Land Reclamation Board (can be abbreviated to "CMLRB"); and the permit number. By the corrective action date, the operator shall submit photo documentation that a proper sign has been posted.

**CORRECTIVE ACTION DUE DATE:** April 5, 2020

**STATUS UPDATE:** *On March 24, 2020, the operator provided photographic evidence that an appropriate mine identification sign has been placed at the mine entrance. Therefore, the Division considers this problem to be abated.*

**INSPECTION TOPIC:** Gen. Compliance with Mine Plan

**PROBLEM:** The current mining plan map needs to be updated pursuant to Rules 6.4.3 and 6.4.4. The operator must provide sufficient information to describe or identify how the operator intends to conduct the operation. Specifically, the operator has created a new access road to the site which is not portrayed on the approved mining plan map.

**CORRECTIVE ACTIONS:** By the corrective action date, the operator shall submit a Technical Revision, with the required \$216 fee, to update the current approved mining plan map to reflect existing and proposed activities at the site, particularly to portray the new access road constructed at the site.

**CORRECTIVE ACTION DUE DATE:** April 5, 2020

**STATUS UPDATE:** *This problem has not been abated at this time.*



**INSPECTION TOPIC:** Gen. Compliance with Reclamation Plan

**PROBLEM:** The current reclamation plan map needs to be updated pursuant to Rules 6.4.5 and 6.4.6. The operator must describe how reclamation will be achieved on all affected land. Specifically, the operator has constructed a new access road to the site which is not portrayed on the approved reclamation plan map.

**CORRECTIVE ACTIONS:** By the corrective action date, the operator shall submit a Technical Revision, with the required \$216 fee (can be same revision submitted for problem cited above), to update the approved reclamation plan map to reflect existing and proposed activities at the site, particularly to portray reclamation of the new access road. If the operator proposes to leave any roads for reclamation, this must be reflected on the reclamation plan map. Additionally, the Division would need to receive a notarized letter from the landowner agreeing to leave the road(s) for reclamation.

**CORRECTIVE ACTION DUE DATE:** April 5, 2020

**STATUS UPDATE:** *This problem has not been abated at this time.*

If you have any questions, you may contact me by telephone at 303-866-3567, ext. 8129, or by email at [amy.eschberger@state.co.us](mailto:amy.eschberger@state.co.us).

Sincerely,



Amy Eschberger  
Environmental Protection Specialist

CC: Michael Cunningham, DRMS