



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

March 25, 2020

Mr. Kent Beach  
Seifert Construction dba Seifert Enterprises, LLC  
198 Range View Loop  
Westcliffe, CO 81252

**RE: Schoolfield Pit, Permit M-1993-027;  
Corrective Action No. 2 Not Complied With**

Dear Mr. Beach,

On March 20, 2020, the Division received via email photographic documentation of the newly posted permit sign, replacing the old sign cited as Problem No. 2 in the inspection report dated March 4, 2020. The original citation is below. The items missing from the sign in the emailed photo documentation are underlined in blue text below:

**INSPECTION TOPIC:** Signs & Markers

**PROBLEM/POSSIBLE VIOLATION:** Problem No. 2: The permit number and operator name required to be on the mine identification sign posted at the entrance of the mine site have faded to the point they cannot be read. This is a problem for failure to post a mine identification sign as required by Section 3.1.12(1) of the rule.

**CORRECTIVE ACTIONS:** The operator shall, at the entrance of the mine site, post a sign which shall be clearly visible from the access road with the following: the name of the operator, a statement that a reclamation permit for the operation has been issued by the Colorado Mined Land Reclamation Board; and the permit number. The operator shall submit photo documentation that a proper sign has been posted by the corrective action date.

**CORRECTIVE ACTION DUE DATE:** 5/04/20

If you need additional time to achieve compliance, please let me know, and call me if you have any questions or need further information at (303)866-3567 x8169.

Sincerely,

Timothy A. Cazier, P.E.  
Environmental Protection Specialist

ec: DRMS file  
Eric Scott, DRMS

