

Newmont Mining Corporation Cripple Creek & Victor Gold Mining Company 100 North 3rd St P.O. Box 191 Victor, CO 80860 www.newmont.com

May 27, 2020

ELECTRONIC DELIVERY

Mr. Timothy Cazier, P.E. Environmental Protection Specialist Colorado Department of Natural Resources Division of Reclamation, Mining and Safety Office of Mined Land Reclamation 1313 Sherman Street, Room 215 Denver, Colorado 80203

Re: <u>Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company; Cresson Project; –</u> <u>May 18, 2020 Aerial Inspection Report Response</u>

Dear Mr. Cazier:

On May 21, 2020, Newmont Corporation's Cripple Creek and Victor Gold Mining Company (CC&V) received the Division of Reclamation, Mining and Safety's (DRMS's) report for an aerial inspection of the site conducted on May 18, 2020. Below are DRMS comments in italics followed by CC&V's responses in bold.

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTINGID#:	MINERAL:	COUNTY:
Cresson Project	M-1980-244	Gold	Teller
INSPECTION TYPE:	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Aerial Inspection	Timothy Cazier	May 18, 2020	08:06
OPERATOR:	OPERATOR REPRESENTATIVE:	TYPE OF OPERATION:	
Cripple Creek & Victor Gold Mining	None	112d-3 - Designated Mining Operation	

REASON FOR INSPECTION:	BOND CALCULATION TYPE:	BOND AMOUNT:
Normal I&E Program	None	\$209,491,188.00
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:
NA	None	DRMS
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:
Clear	Thim alt	May 21, 2020

The following inspection topics were identified as having Problems or Possible Violations. OPERATORS SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF THE PERMIT AND APPLICABLE RULES AND REGULATIONS. If a <u>Possible Violation is indicated, you will be notified under separate cover as to when the Mined Land</u> <u>Reclamation Board will consider possible enforcement action.</u>

INSPECTION TOPIC: Fish & Wildlife **PROBLEM/POSSIBLE VIOLATION:** Problem: Process solution ponding was observed in areas greater than the 3 ft x 3 ft on both VLF1 and VLF2 in multiple areas. The 3 ft x 3 ft ponding limitation is a condition of the approved wildlife protection plan. **CORRECTIVE ACTIONS:** Provide photographic documentation of eliminating the areas of ponded solution by the Corrective Action Due Date. **CORRECTIVE ACTION DUE DATE:** 5/27/20

CC&V has corrected the observed solution ponding identified on VLF 2, as detailed in the below photos.





CC&V has corrected the observed solution ponding identified on VLF 1, as detailed in the below photos. Please note the area identified in Photo 7 of the DRMS report was at the 10,400' elevation; and no ponding was observed in the area when CC&V went to address the DRMS observation. There was a line that needed repair, hence the spray observed in the photo, which has since been repaired.









CC&V acknowledges the DRMS's observations contained in the report and is working to investigate the observed conditions. Should you require further information please do not hesitate to contact Katie Blake at 719.689.4048 or myself at 719.689.4042 or Justin.Raglin@newmont.com.

Sincerely,

PP Kathryn Blake

Justin Raglin Sustainability and External Relations Manager Cripple Creek & Victor Gold Mining Co

JR/kb Ec: T. Cazier – DRMS M. Cunningham – DRMS E. Russell – DRMS P. Lennberg - DRMS B. Bowles – DRMS J. Raglin – CC&V J. Bills – CC&V K. Blake – CC&V W. Conley – CC&V

 $\label{eq:sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_sigma_$