

# RILL AND GULLY INSPECTION REPORT

**C. B. MINERALS COMPANY, LLC**

Location	Coal Ridge #1 Mine
Frequency	After Snowmelt

Date	May 31, 2020
Inspector	Jim Stover

Backfilled Areas	Year Backfilled	Season and Year Seeded
1. Mine Site	1994	Fall 1994
2. East Cut Slope, East Portal Repair, Dozer Slots	1995	Fall 1995
3. Pond and Borrow Area	2015	Fall 2015
4		
5		
6		

Area	Rills & Gullies	Depth*	Width	Description of Action Taken
1	None			
2	None			
3	None			
4				
5				
6				

\* If depth is over 9-inches, backfilling is required.

