

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: JUNE 9, 2020

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>


PICTURE TAKEN

✓

Comments:

SOME RAIN OVER THE WEEKEND.

INSPECTED BY STAN O.



Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.

Date of Inspection: JUNE 15, 2020

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>


PICTURE TAKEN

✓

Comments:

FIRST GREEN STARTING TO SHOW ON PARTS OF SEEDED AREA.

INSPECTED By STAN O.



6/15

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.


Date of Inspection: MONDAY JUNE 22, 2020

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>


Comments:

RAIN ON THURSDAY 6/18 PM. LIGHT SHOWERS ON SUNDAY
6/21. SEED STARTING TO GROW.

Inspected by: STAN OPPERMAN



20/9



4/2/2

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.


Date of Inspection: JUNE 29, 2020

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

FRIDAY JUNE 26 GOLDEN HAD HEAVY RAIN ± 1.5". STORM WAS WIDE SPREAD OVER THE DENVER AREA. ROCK BERMES, STORMWATER POND, ETC. ALL WORKED WELL. A FEW MINOR WASH AREAS ON SOUTH SLOPE WHERE WATER RAN OFF EXISTING GRASS. NO NOTICE OF NEW GRASS GROWTH. THIS RAIN SHOULD HAVE BEEN GOOD TO HELP WITH THAT.


Inspected by: STAN O.



6/28



6/29



6/29



6/29

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.


Date of Inspection: WED. JULY 8, 2020


	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>


Comments:

HOT AND DRY. SEED PROGRESS IS SLOW. SLOPES ALL LOOK GOOD.

Inspected by: STAN OPPERMAN







31/20

Asphalt Paving Company

Ralston Quarry
6569 Highway 93
Golden, CO 80403

Slope Remediation

1.1.1 Monitoring Plan

The slide area will be monitored following slope stability construction activities. This monitoring will consist of visual inspections and surveys conducted by APC and Ground Engineering. APC will inspect the area weekly following construction. If any emergency conditions, such as further failures, are discovered, DRMS will be immediately contacted.


Date of Inspection: July 14, 2020

	Yes	No
Slope movement	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Noticeable cracking	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Stormwater features intact and working properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitor seed growth progress	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any condition requiring APC attention or mitigation	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Any condition requiring DRMS notification	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Pictures Taken	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

SOUTH PART OF SLOPE IS SHOWING MORE SEED GROWTH.
FRIDAY JULY 10, 2020 I TOOK PICTURES FROM THE TOP.
THEY ARE IN STORED FILE.

Inspected by: STAN OPPERMAN



7/14



2/12