



# ESCO Sand and Gravel, LLC

32045 Castle Ct, STE 104

Evergreen, CO 80439

Phone: 303.674.3385 Fax: 303.674.9967

Date: 08/04/2020

**Date: 8/14/2020 (Inspection Topic #2-Complete)**

Name: Dave Marshall

Company: ESCO Sand and Gravel, LLC

Address: 32045 Castle Ct, STE 104

Evergreen, CO

80439

## **RE: Inspection- Kattenberg Pit M-2004-017**

Dear Mr. Peter Hays- Division/DRMS

Thank you for the opportunity in allowing us to respond to the Corrective Actions provided by you on June 16, 2020.

### **#1 INSPECTION TOPIC: Backfilling & Grading**

**PROBLEM:** The approved Mine Plan requires the Operator to maintain a 25-foot offset from the property line and mine the perimeter at the final 3H:1V slope. The northeastern highwall previously repaired by a former Operator has eroded to within 2 feet of the permit boundary and exceeds the approved perimeter mined slope of 3H:1V.

**CORRECTIVE ACTIONS:** The Division will require the Operator to backfill the highwall to establish the required

25-foot offset from the eastern boundary and the required 3H:1V slope and provide evidence within 30 days of the mailing date of this report.

**CORRECTIVE ACTION DUE DATE:** 8/5/20

**Corrected** 7/29/2020





# ESCO Sand and Gravel, LLC

32045 Castle Ct, STE 104

Evergreen, CO 80439

Phone: 303.674.3385 Fax: 303.674.9967

In response to the Inspection Topic "Signs & Markers, we are respectfully requesting additional time to correct.

Reason: We have made many attempts to contact multiple survey companies and have been unsuccessful. Many of the survey companies we reached out to, did not return our phone calls and/or the companies that we were able to contact, were not able to perform the work until after the correction date. We have scheduled a survey company to perform the work on 08/14/2020 and are respectfully requesting a 30-day continuance to complete the remaining work.

**We have completed Inspection Topic #2 on 8/13/2020 (Please See Reference Photos Below)**

## **#2 INSPECTION TOPIC:** Signs & Markers

**PROBLEM:** The affected area boundary markers are missing or incorrectly placed. This is a problem for failure

to maintain boundary markers around the affected area as required by Rule 3.1.12(2).

**CORRECTIVE ACTIONS:** The Operator shall conduct a survey and replace the boundary markers in the correct

location(s). The Operator shall provide proof to the Division that this has been done by the corrective action

date.

**CORRECTIVE ACTION DUE DATE:** 8/5/20

**Date Completed:** 8/13/2020



Respectfully,

Dave Marshall

ESCO Sand and Gravel, LLC

[Dmarshall@escomailbox.com](mailto:Dmarshall@escomailbox.com)

Cell: (303) 434-4346