Minerals Reclamation Permit Annual Report



General Information

Disclaimer

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following is due:

Select Permit Number *

Only Permit Numbers with currently due Annual Reports and Fees will be listed. If nothing appears in the dropdown box below, there are no annual fees or reports due for any of your permits.

M2018054

Select Anniversary Date *

11-05-2020

PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee *

✓ I understand and agree to the terms

11-05-2020

General Information

Permittee Name

SEMA Construction, Inc.

Operation Name

Diehl Borrow Pit

Larimer

Permit Number	Fee Due	Permit Acreage
M2018054	504.00	26.95
County	Anniversary Date	Current Bond Amount

88112.00



Contact Information

Here is the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

- 1. Upon submission of this form you will be presented with a link to the contact information update form.
- 2. There is a question asking about the accuracy of this information at the bottom of this page. Indicating that it is inaccurate will send an e-mail to notify your administrator to make the appropriate changes.

Permittee Contact Information

Permittee Contact Name

Cameron Mang

Permittee Company

SEMA Construction, Inc.

Permittee Address 1

7353 S Eagle St

Permittee Address 2

Permittee City Permittee State Permittee Zip

Centennial CO 801120000

Permittee Phone # Permittee Fax #

3036272600 3036272626

Permittee Contact Email Address

dnr_drmsminadmin@state.co.us

Permitting Contact Info

Permitting Contact Name

H. Bruce Humphries

Permitting Company

Regulator Permits Management, Inc.

Permitting Address 1

25049 E Alder Dr

Permitting Address 2

Permitting City Permitting State Permitting Zip

Aurora CO 800160000

Permitting Phone # Permitting Fax #

Permitting Contact Email Address

hlhumphries2@comcast.net

Inspection Contact Info

Inspection Contact Name

Cameron Mang

Inspection Company

SEMA Construction, Inc.

Inspection Address 1

7353 S Eagle St

Inspection Address 2

Inspection City Inspection State Inspection Zip

Centennial CO 801120000

Inspection Phone # Inspection Fax #

3036272600 3036272626

Inspection Contact Email Address

dnr_drmsminadmin@state.co.us

Is the Permitting Contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *





Annual Report Questions

0.0

Information contained in this report is required and will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1. Is the site identification sign posted in accordance with Rule 3.1.12(1). *
2. Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2). *
3. Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? * If "YES," please note time limits related to completion of reclamation, Rule 3.1.3. Yes No
4. Please enter the date of last activity at the mine (excavation, processing or hauling). Or, if activity has not yet begun, please indicate so.*
No activity yet [®] Yes, activity has begun 6/1/2020
5. Does the mine operate more than 180 days per year? * If "NO", please review Rule 1.13 to assure that your mine is in compliance. Yes No
6. Has this mine been granted approval of TEMPORARY CESSATION Status? * ○ Yes ○ No
7. Has this mine been granted approval for INTERMITTENT OPERATION? * (?) Yes No
For the following questions, please note that numeric values must include one decimal place, such as "0.0" for zero acres, or 10.2 instead of 10.23.
8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 26.9
9. Number of acres that were newly affected during the current report year * (?)
10. Number of acres that were reclaimed during the current report year. * (?) 26.9
11. Estimated new acreage to be affected in the next report year. * (?) 0.0
12. Estimated acres to be reclaimed in the next report year. * (?) 0.0
13. Total acres in various stages of reclamation, since permitted mining activities began:
Total acres backfilled * (?)

Total acres seeded with approved mix * (?) 26.9 Seed Application Method * Drill seeding Total acres fertilized with aproved fertilizer * (?) 26.9 Fertilizer Application Method * Tractor towed spreader Total acres with topsoil replaced * (?) 26.9 Topsoil replacement depth (in.) * (?) 6.0 Total acres mulched with approved mulch * (?) 26.9
Total acres fertilized with aproved fertilizer * (?) 26.9 Fertilizer Application Method * Tractor towed spreader Total acres with topsoil replaced * (?) 26.9 Topsoil replacement depth (in.) * (?) 6.0 Total acres mulched with approved mulch * (?) 26.9
Fertilizer Application Method * Tractor towed spreader Total acres with topsoil replaced * (?) 26.9 Topsoil replacement depth (in.) * (?) 6.0 Total acres mulched with approved mulch * (?) 26.9
Tractor towed spreader Total acres with topsoil replaced * (?) 26.9 Topsoil replacement depth (in.) * (?) 6.0 Total acres mulched with approved mulch * (?) 26.9
Topsoil replacement depth (in.) * (?) 6.0 Total acres mulched with approved mulch * (?) 26.9
6.0 Total acres mulched with approved mulch * (?) 26.9
26.9
Mulch application rate (tons/ac) * (?) 2.0
Mulch Application Method * Crimping, with tractor Previous Proceed

Annual Report Questions

Annual Fee Payment

Annual Fee Payment

Payment Confirmation Number * (?)

153142226

Signature

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans. *

I Agree

If you do not see the "Submit" button after completing your report, try to un-check and then re-check the "I Agree" box.

Previous